SURVEY & REMONUMENTATION

OCT 0 3 1996

Register's Office LAND CORNER RECORDATION CERTIFICATE Gogebic County COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970. Received for record the For corners in 10 TH day of JUNK Gogebic Located In: Corner Code ## A. D. 19 96 at 9140 o'clock A m., and recorded in T 48NR 47W 1. Public Land Survey T 48NR 48W T 49NR 47W T 49NR 48W Liber 5 Of CORNERS M-1on page 352 among Colling Deputy ___ T ____ R ____ 2. Property Controlling Register of Deeds S ____ T ___ R ___ S ___ T ___ R ___ in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat _ 4. Lot No. 5. Private Claims ___ NE Township Corner T.48N, R.48 W <u>May 29,</u> I, John P. Goss , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Original corner established by William Ives in 1847. Set Post.

Original bearing trees: Cedar 22" N 320 W 25 links Cedar 12" S 640 W 22 links 22 links.

Richard Drahn and John Goss in 1978 found original corner position marked by a 1" diameter pipe at recorded bearing and distance from the remains of the two original bearing trees. They recorded said corner position in Liber 1 page 408 of Land corners for Gogebic County. They established the following bearing trees and reference objects. A 1½" I.D. by 4½' long, concrete filled iron pipe with 3" circular brass tablet markes corner position. Witnesses are B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

N.62° E. N.88° W. 12" Yellow Birch 34.01 8" Red Maple 22.81 N.150 W. 8" Cedar

I found the 12" iron pipe with 3" circular brass tablet set by Drahn and Goss and it checked with thier witnesses. I updated the corner monument and accessories as noted below to state and county specification.

Act 74 reseach on file.

on this certificate.

Rechard h. Dicalin 6/6/96
COUNTY REPRESENTATION

SURVEYOR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the 12" iron pipe with 3" brass tablet, stamped T.48-49N., R.47-48 W.; S-1,S-6,S-31,S-36; 1978, R.L.S. 23509, from which I established the following bearing trees and reference objects. OF MICHICAL

N.620 E. 33.991 15" Yellow Birch N.880 W. 9" Red Maple 22.771 N.150 W. 10" Cedar 31.50 S.16° W. 6" Cedar S.620 E. 6'Rail & Sign

Fed. No. A-25

Note: D.H. Nail & tag in all trees.

Signed by John O Yos Date May 30, 1996

Surveyor's Michigan License No. 23509

FORM APPROVED BY MICHIGA FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975