## SURVEY & REMONUMENTATION -

OCT ( 3 1996

Canalia M

 $\_$  , Recorded Plat  $\_$ 

For

5. Private Claims \_\_\_

expressed below:

## LAND CORNER RECORDATION CERTIFICATE

Hegister'	's Office		
Register' Cogebic	County	1	SE

corners in	Filing Require	Filing Requirement of Act 74, Mich. P.A. 1970			
Gogebic	Located In:	Corner Code ##	A. D. 1996 at 10:30 o'clock		
Public Land Survey	т 49N R 47W т R	F-7	Am, and recorded in Liber5olCarnars		
	T R T R		Ramono Coliuns, Deputiz		
Property Controlling in Section	S T R S T R		Register of Doods		

Property in Sec. S T R R Register of Deeds Stamp & File Number

1/4 cor. comm. to 16 & 21		
John P. Goss in a field survey on		
do hereby certify that under requirements of P.A. 74, Michi	igan P.A. of 1970, the corner	points mentioned
in lines 1 and 2 above were in conformance with regula	ations and rules therefore a	as required in the
current manual of survey instructions of the United State	s Department of the Interio	or, Bureau of Land
Management or by a decree of a Court of Law and/or that the	he corner points mentioned	lin lines 3, 4 and 5
above were in conformance with the rules of the Michigan	•	•
Court of Law established re-established monument	ied re-monumented reco	wered found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	<u> </u>	B	C	D	E	F	G	Н	ا ا	K	L	
2		6		5	_	] 4 —	L			2	] 1	
3	_	L		_	L	L					$\dashv$	
4		ļ 7—	L	8 —	_	 9 —	Ļ,	0	1	,	į	2
5		1	_	L.		_	<u> </u>		_			
6	L.	ا 18—	<u>_</u> ,	]  7	L,	  6	L,	5	L,	4	 1	3
7		1	L	_	L	<b>L</b>	<u> </u>		<u> </u>			
8	ļ	 19	-2	0	2	Γ !1	_2	  2	2	3	2	4
9	L	↓_	_	_	_	<u> </u>	_	<b>!</b>			$\dashv$	_
10	į;	 30	2	9	2	8	<u> </u> 2	7	2	6	2	5
1.1	_	┼	ļ	-	_	-	├-		L.		-	<u> </u>
12	-:	31	<b>-</b> 3	2—	3	  3—	<b>—</b> 3	4	<u> </u>	5—	3	6
12	ı	1	ı	l	1	l	I .	l i		i		

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Ives on Sept. 30, 1848. Set post. Original bearing trees: 12" Hemlock N 61° E 10 links 12" Hemlock S 46° W 15 links.

John Garske, found a 3/4 inch iron pipe at location of corner. He set a 2" iron pipe with 2" brass cap marked to indicated the corner position. He recorded said corner location in Liber 2 on page 511 of Land Corners for Gogebic County. He established the following bearing trees and reference objects. 6" Y. Birch- S 52° E- 16.11; 6' Maple N 440 E- 25.22'; 8" Maple S 78° W- 19.28'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the 2" iron pipe with 2" brass cap and it checked with Garske witnesses. I updated the accessories as noted below to state and county specification.

Act 74 research on file.

Reclard R. Dedan 8/8/96
COUNTY HEREBENHATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the 2" iron pipe with brass cap. I established the existing and new bearing trees and reference objects.

8" Y. Birch	S 78° W	19.28'
7" Maple	S 44° E	25.22'
8" Maple	N 52° E	16.11'
8" Maple	N 23° W	16.15'
6' Rail & Sign	N 080 M	1.19



Date Queg. 5, 1996