1993

COMMISSION

For corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

	Gogebic County Ss.
TE	Received for record the
70	16th day of DECEMBER
	A. D. 19 93 at 2:25 o'clock
	$\underline{\mathcal{P}}$ m., and recorded in
	Liber 4 Of CORNERS
	on page 308
	Betty Janie Deputy
	Register of Books

Register's Office

Register of Deeds Stamp & File Number

Property in Sec. S T R _			
4. Lot No, Recorded Plat			_
One-quarter corner S-15 & 14.			
	December 7	93	
I, <u>John R. Garske</u> , in a field survey on <u></u> do hereby certify that under requirements of P.A. 74, Mich			

I, John R. Garske , in a field survey on _______, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Original survey by William Ives, Deputy Surveyor, on September 27, 1848. Set quarter post at 40chs (south to north) bearing trees:

10" sugar - S40°E - 16 links 5" sugar - N40°W - 16 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 3/4" iron pipe with 2" cap set by Keweenaw Land Association which replaced a wood post found by Keweenaw Land Association. Corner position was noted to us by Pat Kamarainen, Forester with Keweenaw, as existing for over 40 years. An old blazed sugar maple bears N32°W, 9.40 feet with an old poster grown into the tree. I accepted this corner position as marking the original corner. No evidence of the original bearing trees could be found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1 3/4" iron pipe with 2" cap with a standard Bernsten 2 1/2" aluminum pipe 30" long with 3 1/2" aluminum cap stamped: County Remonumentation; T49N, R47W; 1/4 cor.; S-15; S-14; 1993; RLS 28410. Established the following bearing trees and reference objects:

10" sugar maple w/old blazes - N32°W - 9.40 feet

4" yellow birch - S60°E - 4.80 feet

3" sugar maple - N54°E - 7.65 feet

3" sugar maple - S23°W - 6.36 feet

Steel sign post - west - 1.24 feet

Date

28410

REVISED JAN., 1983 REVISED JAN., 1983

OF MIC

JOHN R.

garske

LAND

SURVEYOR No.

Surveyor's Michigan License No. 28410

Signed by