1993

COMMISSION Register's office Gogenic county sa. LAND CORNER RECORDATION CERTIFICATE Received, for foord the Filing Requirement of Act 74, Mich. P.A. 1970 16 79 day of December For corners in Gogebic Located In: Corner Code ## A. D. 1993 __at 2 25 o'clock P m., and recorded in 1. Public Land Survey Section 15 T 49N R 47W. Liber 4 Of CORNERS on page 309 sare Den **Property Controlling** Register of Aleeds in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No. , Recorded Plat 5. Private Claims _ Section corner common to S-15, 14, 23 & 22. May 29 ı John R. Garske _ , in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10

Original survey by William Ives, Deputy Surveyor, on September 27, 1848. Set meander post with bearing trees:

10" hemlock - S43°E - 10 links 12" hemlock - N59°W - 15 links

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Description of original monument and accessories and/or subsequent restoration:

on this certificate.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found stump mound with root holes with hemlock bark evident at 12" hemlock BT location. Found decayed remains at other hemlock BT location. Set monument in center of skid trail from decayed BT remains. Keweenaw Land Association said that an old post existed there many years ago but apparently destroyed as old trail runs through area.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Bernsten 2 1/2" aluminum pipe with 3 1/2" aluminum cap stamped: T49N, R47W; S-15; S-14; S-22; S-23; 1993; RLS 28410. Established the following bearing trees and reference objects:

16" S. maple - N02°W - 10.28 feet 15" yellow birch - S71°E - 16.79 feet 4" S. maple - S29°E - 15.90 feet 15" S. maple - S60°W - 12.80 feet Steel sign post - east - 1.28 feet

Surveyor's Midhigan License No. _

12

JOHN R garske CMAL SURVEYOR No. 28410

APPROVED BY MICHIGAN STATE HOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983