SURVEY & REMONUMENTATION

OCT 0 2 1396

COMMISSION

| For corners in ogebic | | | R RECORDATION CERTIF ment of Act 74, Mich. P.A | 1970 Gogebic County | |
|-----------------------|---|---|---|---|--|
| | | Located In: | Corner Code # | leceived for record the day of August | |
| | (County) | | | A. D. 19 96 at 11:15 o'clock | |
| 4 | Dublic Land Come. | т ^{49N} в ^{48W} | D-11 | | |
| 1. | Public Land Survey | T R | | A m., and recorded in | |
| | | T R | | Liber 6 of CORNERS | |
| | • | T R | | mge 22 | |
| 2. | Property Controlling | ST R | | Ramona Colums Departy | |
| | in Section | S T R | | Register of Deeds | |
| 3. | Miscellaneous | S T R | | Decistor of Danda Starry 9 File Number | |
| | Property in Section | S R | | Register of Deeds Stamp & File Number | |
| , | Éat Na B | ecorded Plat | | | |
| | | ecorded Flat | | A B C D E F G H I J K | |
| | | | | 2-6-5-4-4-4-2-1 | |
| | 1/4 Corner 29&32, T49 | N, R48W. | | 3 | |
| | John R. Garske | ň | fay 16 95 | 4-7-4-9-10-11-1 | |
| ١, . | | , in a field survey on | , 19 | , 5 | |
| | | uirements of P.A. 74, Michigan P.A onformance with regulations and n | | | |
| | | of the United States Departm | | | |
| Ma | nagement or by a decree of | a Court of Law and/or that the co | ner points mentioned in lines 3, 4 | and 8 19 20 21 22 23 | |
| | | with the rules of the Michigan Bo | | | |
| | cree of a Court of Law; estail expressed below: | blished, re-established, monument | ea, re-monumentea, recoverea, to | ound 10 30 29 28 27 26 | |
| | • | ners, all in the same town and | range may be recorded | 11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1 | |
| | on this certificate. | nors, an in the same town and | range, may be recorded | 12 31 32 33 34 35 | |
| | | | | 13 | |
| Α. | Description of original | monument and accessories a | nd/or subsequent restoration: | | |
| | - 1/4 post V7°-40'E | | | | |
| | Original Bearing Tro | ees: Sugar 7"-N37°E-23 links | | | |
| | | DO 8"-S85°W-22 links. | | | |
| | P. pole - N55°W - 6 P. pole - S44°E - 41 | .79 feet | orded corner, L2, pg. 587. Tie | s: _. | |
| | S.E. Cor. Garage - I | N39°E - 37.06 feet | | | |
| В. | • | vidence found and/or method | | - | |
| | I found the P.K. nail just county specifications as | north of the centerline of Lake noted below. | Road with the accessories note | ed above. I updated the corner to state and | |
| | ., . | | | | |
| | | • | | OF MICEN | |
| | P.A. 74 Research on file | | | C. C. | |
| | F.A. /4 Research of the | • | | JOHN R. | |
| | | | | GARSKE | |
| | | | | LAND | |
| | | | • | SURVEYOR No. | |
| | | | | 28410 | |
| | | | | | |
| | | | | A LAKO STATE | |
| C. | Description of monume | nt for comer and accessories | established to perpetuate loc | ating the position of the comer: | |
| | | | • | | |
| | I replaced the P.K. nail v | vith a 3" brass cap stamped: 1 | 4 T49N, R48W, S.32,S.29,19 | 95, RLS 28410; cemented into the pavement | |
| | from which I established the following reference objects:. | | | | |
| | 2 1/2" Aluminum pipe with 3" aluminum cap stamped: County Remonumentation, R.M T49N, R48W, S.32, S29, 1995, | | | | |
| | | -32.42 with steel sign post 0.9 | 6'. | | |
| | P. pole - N55°W - 60 P. pole - S44°E - 41 | | A PEER GROUP APPRO | na an | |
| | S.E. Cor. Garage - N | | 1) 10 N 1) | r.H. nate. | |
| | - · · · · · · · · · · · | Kun | Kard Y. William 81 | 14196 | |
| | | | COUNTY BEPRESENTA | LLYE | |
| | | ; | , · · · · · · · · · · · · · · · · · · · | | |
| | | DEN | b | 0-1-01 | |
| Sig | ned by | -TJURNE | Date | 0-4-76 | |
| Sur | veyor's Michigan License | No. 28410 | FORM APPF | OVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 | |
| | V | • | | REVISED MAY 14, 1975 REVISED JAN., 1983 | |