Carmer & EMONUMENTATION

MAY 1 8 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office Cogebic County

Received for record the 12th day of ORCEMBER A. D. 19 96 at 2:30 o'clock P m., and recorded in Of GORNESS 6 iber

92 on Dage_ Ramone L. Couins Daputy Register of Deeds

Register of Deeds Stamp & File Number


For corners in Corner Code # Located In: Gogebic 45W T49NR 750NR 1. Public Land Survey 45W 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

_, Recorded Plat 4. Lot No. 5. Private Claims

Section corner common to sec's. 5,6,31 & 32

I. <u>Tohn P. Goss</u>, in a field survey on <u>Octo 8</u>, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines t and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the line United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and lor that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt in Sept. 1847. Set Hemlock post

Original bearing trees: Sugar 12" N 080 E 33 links

Original bearing trees: Sugar 12" N 080 E 33 links

Lynn 20" N 540 W 35 links

Lynn 20" N 540 W 35 links

Keith Sackett, RIS for DNR round a 2" I.D. iron pipe on July 31, 1980, marked

T.49-50 N, R.45 W., S-5,S-6,S-31,S-32; 1959. He accepted said corner and

T.49-50 N, R.45 W., S-5,S-6,S-31,S-32; 1959. He accepted Said County. He

recorded it in Liber 2 page 124 of Land Corners for Gogebic County. He

established the following bearing trees and reference objects. 8" Y. Birchestablished the following bearing trees and reference objects. 8" Y. Birch-S 18° E- 21.0'- S-5,NBT; 5" Maple-S 85° W- 15.7'-S-6, NBT; 6" Ash- N 63° E

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the 2" I.D. iron pipe with marked cap and it checked with K. Sackett witnesses. I updated the accessories as noted below to state and county specification.

Act 74 research on file.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the 2" Iron Pipe Marked T. 49-50 N, R.45 W.; S-5,S-6,S-31, S-32, 1959. I established the existing and new bearing trees and reference objects.

s 18° E (dead) 21.01 (2)85° W 8" Y. Birch 16.281 S 6" Maple (3) 26.70 N 63° E 10" Ash 15,901 530 E 4" Y. Birch 23.94 350 W N 9" Maple 2.1' Due S. 6' Rail & sign

Measurements to No. 2,3,4 & 5 are to nail in side

tree. John P Loss of tre Signed by _ 23509 Surveyor's Michigan License No._

Date Oct 9, 1996



Fed. No. Z-5