LAND CORNER RECORDATION CERTIFICATE

ing Requirement of Act	74,	Mich.	P.A.	1970
	ing Requirement of Act	ing Requirement of Act 74,	ing Requirement of Act 74, Mich.	ing Requirement of Act 74, Mich. P.A.

STATE OF NICHIGAN GRATIOT COUNTY RECORDED

GRATIOT	Located In:	Corner Code #
(County)		
MASHINGTON TWD		

22 JUL 99 11:56 A.M.

JANET H. DAVIS REGISTER OF DEEDS

R 2. Property Controlling R

_, Recorded Plat

1. Public Land Survey

4. Lot No.

5. Private Claims

Register of Deeds Stamp & File Number

5

8

17

20

20

32

. 4 ...

16

21

28

-33

10

15

22

27

34

12

13

24

25

36

11

23

26

35

1 5

6

7

18

10

31

2

Q

10 30

11

12

13

in Section R 3. Miscellaneous Property in Sec. S R

R 2W

R

, in a field survey on JUNE 3, DAVID R. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:

1. CORNER NOT SET IN GLO SURVEY.

2. CORNER REFERENCED IN SURVEY BY R.J. FRAKER, COUNTY SURVEYOR, DATED DEC. 1877. WITNESSED BY: LYNN 10" EAST 3 1/2L (2.31'). ELM 5" S 50° E 82L (54.12'),

SURVEY SHOWS DISTANCE SOUTH OF 39.07CH (2578.62'), DISTANCE WEST OF 40.14CH (2649.24'), DISTANCE EAST OF 40.14CH (2649.24').

- 3. NO OTHER REFERENCES FOUND.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND #4 REBAR WITH SMASHED CAP 0.1' (30cm) BELOW GRAVEL SURFACE. TRAVERSED ENTIRE SECTION AND DETERMINED THAT FOUND IRON CLOSELY MATCHES F-13 NORTH STAR TOWNSHIP, BEING ABOUT 0.06 FT. (18cm) WEST OF MID-POINT BETWEEN E-1. AND G-1, HOWEVER IT LIES ABOUT 1.28 FT. (0.39m) SOUTH OF TRUE TOWNSHIP LINE. F-1 LIES 8.75FT. (2.667m) WEST OF F-13. COULD FIND NO EVIDENCE OF THE LOCATION OF F-1 AS A 36" (0.914m) CONCRETE STORM PIPE CROSSES GRANT ROAD AT THAT LOCATION. SET STANDARD REMON. PIPE CUT TO LENGTH OF 0.88FT. ((0.268m) DUE TO SHALLOW CONCRETE STORM PIPE ROSSING. STANDARD PIPE SET IN 12" (305cm) STEEL AUTOMOTIVE WHEEL HOUSING AND SET WITH MANY ROCKS.

Description of monument for corner and accessories established to perpetuate locating the position of the corner. '-1: TOWN 9 NORTH, RANGE 2 WEST, WASHINGTON TOWNSHIP, GRATIOT COUNTY. SET MODIFIED REMON. PIPE, SET IN TEEL COLLAR AND WITH SMALL ROCKS, OVER TOP OF CONCRETE STORM PIPE. WITNESSED BY:

ET #4 REBAR WITH CAP #30090, s 72° W, 43.00' (13.107m) s 70° E, 43.00' (13.107m) ET #4 REBAR WITH CAP #30090,

43.00' (13.107m) ET #4 REBAR WITH CAP #30090, N 74° W, -13, NORTHSTAR (STANDARD PIPE), N 85° E, 8.75' (2.667m)

TAINLESS STEEL 30" (762mm) X 2 3/8" (0.65mm) PIPE WITH A BRASS CAP STAMPED

EARINGS GIVEN ARE MAGNETIC. STANDARD MONUMENTATION CONSISTS OF A BERNTSEN GRATIOT COUNTY REMONUMENTATION", P.S. #30090.

OF MICHIGAN DAVID R. LOHR **PROFESSIONAL** SURVEYOR No.30090 POFESSIONA

Date 7/19/99

rveyor's Michigan License No. 30090

ACCEPTED BY THE GRATIOT COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 7/2/27

REVISED MAY 14, 1975 REVISED JAN., 1963 REVISED JAN., 1963 REVISED OCT, 1965 ADAPTED FOR WORD PROCESSING JAN, 1966

WG Tunder William Tholor De Thomas