LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	Co	RNER CODE NUMBER	7
1. PUBLIC LAND SURVEY	29 T. 9 \$., R. 2	<u>E-</u>	10, E-11	
2. PROPERTY CONTROLL ING IN SECTION	N. S., R N.			
	N. S., R			
4. LOT NO	RECORDED PLAT			
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Russell L. Roon, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines I and 2 above were, in a field survey on				
A. Description of original monument and accessories and/or subsequent restoration:				
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:				
E-10 Set halfwa and E-11,	y between E-9 and on line.	t-11	Found Iron in mo	nument box.
C. Description of monume	ent for corner and accessories esta	blished t	o perpetuate locating the	position of the corner:
monument b S 12° E 66.40' bound bridge o S 23° W 66.33'	e with plastic cap in ox. NW Cor., E. Rail, N. ver Mapie River NE Cor., W. Rail, N. ver Mapie River	E-11	Iron in monument East 50.0' Ancho West 1.3' C N. South 232' C Cro	r post in fence cor. bound US-27
SIGNED BY			DATE	
SURVEYOR'S MICHIGAN	REGISTRATION NO			(SEAL)
FOR STATE AND UNIT		- 1.2		$\chi_{i} = U + 1$
SIGNED BY	CHIEF, OF BURVEY PARTY		DATE	- Control of the
APPROVED AND SIGNED BY . MICHIGAN REGISTEREO LAND SURVEYOR (SEAL)				
				11 (1) (1) (1) (1) (1) (1) (1) (1) (1) (
SURVEYOR'S MICHIGAR	REGISTRATION NO	13593		/ / / / / / / / / / / / / / / / / / / /