LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY 25	. T. 9 3. R. 3 w.	M-9, M-10	7
2. PROPERTY CONTROLL- ING IN SECTION-	,T N. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. E. W.		
4. LOT NO, RECOR	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in line re-established, monumented, re-mand rules therefore as required in Bureau of Land Management or b and 5 above were, in a field survey as expressed below and in conform Decree of a Court of law:	es 1 and 2 above were, in a conumented, recovered or rethe current manual of survey a decree of a court of law on	field survey on March estored as expressed below and ey instructions of the United St. Furthermore, that the corner, 19, found, recovered, rest Michigan State Board of Registr	
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence M-9 Found 3/4" I ron monument box.		lied in restoring or re-establishin Set halfway between and SE Cor. 25 and o	NE Cor. 25
C. Description of monument for o	corner and accessories estab	lished to perpetnate locating the	position of the corner:
M-9 3/4" iron pipe i West 7.2' © State Ro North 9.0' © Taft Roa S 40° W 67.14' Fence North 82.32' NW Cor.,	oad ad to west a Cor.	atuminum N 28 ⁰ E South 85, North 80, (1" ti	cipe in concrete with cap. 81.89' 30" Triple Maple 11' 10" Willow 04' W 1/4 Sec. 30 ron in concrete with
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN REGI	ISTRATION NO.		(SEAL)
FOR STATE AND UNITED STA			As the
SIGNED BY	CHIEF-OF-SURVEY PARTY	DATE.	·
APPROVED AND SIGNED BY	MICHIGAN REGISTERED L	DATE DATE	(SEAL)
SURVEYOR'S MICHIGAN REGI	ISTRATION NO1	3593	A Company