SURVEY & REMONUMENTA	TION										
I [TIAICS SCALEGE IN S	GRA	ATIOT COUNTY	REMONUMEN	ITATION PROGR	AM _{IBE}	353	8	PAGE 1	502		
AUG 3 1 1994c											
ACHRICOIA	a 0	AND CORNER	RECORDATION	ON CERTIFICATE							
COMMISSIO	ÎÆ	Filing Require	ment of Act 74	, Mich. P.A. 1970							
For corners in						GF	RAT!	0T G	0. MI	CH.	
Gratiot	Located	in:	Corner Code #				RI	ECOR	DED		
(County)					,	വെമ	uo 1	10	om 1	ດ ດວ	
						ח דכ	UU .	LJ	uu T	.0 08	
Public Land Survey Se	c 5 T <u>10</u> T	R_Z R	C-3, SW Co	[\cap		مماريد	_		
	Ť	R R		į.			enc	文『N ISTER ()	F DEFDS	نمين	1
O Description O						U	NLU	io iun o	1 hrrad	•	`
	T T		· · · · · · · · · · · · · · · · · · ·		•	£ D	J_ C4	9	Ella k	lumbar	•
3. Miscellaneous S	T	. R			gister o	r Deed	18 36	amp o		- Tunnber	
Property in Sec. S	T	R									
4 Lot No. Reco	rded Plat						n	τ α	<u>.</u> ⊔ 1	JK	
4. Lot No, Recorded Plat						1	1				
					1	6	5	· 4·	3	2	1
					3	-		9 .	10	11	- 12
I, William Tingley		a field surv	ey on <u>July_27</u>	7. 1994	5	7 .	8	.	D .	'	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					-	18	17	16	15	14	13
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					7						
above were in conformance wit	h the rules of th	ne Michigan Board	of Land Surveyors	or by a Decree of a	8 1	19	20	21	22	23	24
Court of Law; established, expressed below:	re-established,	monumented, re-	-monumented, rec	overed, fourid as	9						0.5
NOTE: Not many than A and		ha sama tawa ar	ad maga may h	recorded	1 7	30	29	28	27	26	25
NOTE: Not more than 4 co on this certificate.	orners, all in t	ne same town ai	id range, may be	e recorded	11	31	32	33	34	35	36
. B. Strang Calabi		and-day and	or subsequent re	otorotion:	13				<u> </u>		
A. Description of original n July 21, 1852, Austin Burt,	Deputy Surve	yor, GLO Notes	or subsequent re	Storation.							
Intersect 3 links West of	old corner							*			
	S80-1/2°W S5-1/2°E	37 links 45 links									
April 1871, D.W. Attenburg	, County Surv		ge 274								
Stone old corner found S. Ash 8" S	! 73-3/4°E	67-1/4 lini	KS.								
December, 1874, D.W. Atte				ACCEPTE	n BV TH	E CDA	TIOT	COLIN	TV OU	חעבע הו	FFD
Same as above October 1880, Thomas H. I	Harrod Count	v Surveyor Libe	er C. Page 51	GROUP AS	S THE O	FFICIA	L CO	RNER	UNDER	MICHIO	GAN
Stone Corner	iairou, oouiii	, 00.10101, 2.00	, o, . ago o .	PUBLIC AC	T 345 OF	1990 A	MAT	EETING	HELD	SACO	59
Elm 8"		5-1/2 feet 8-1/2 feet		•		(\mathcal{U})		ine 1	uce	Lyn	
Sugar Maple 8" No Date, County Surveyor			age 100, 101			Y	lilliam	Tingley,	PS, Ch	airman	
Stone Corner East Bridge Wall	South End	30-1/2 feet									
West Bridge Wall	South End	31-1/3 feet									÷
No Date or Name Given, G	ratiot County	Road Commissi	on, Record of M	inutes of Survey				THE PERSON	MINT HERE	2	
Stone corner Maple 12"	S50°W	555-1/2 links					A. S. C. C.	ME)FMICA	16	
Does not match Liber B, P	age 47		Continue	on back		Á	*	Wall	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
B. Description of corner e	vidence found	and/or method at				-	* *	TIN	LIAM (IGLEY	, , , , ,	
Found Pole Barn Spike pe	r LCRC Liber:	2, Page 220, 3 fe	et South and 1.3	feet West of True	Corner		LICE	PROF SUF	ESSIONAL VEYOR	د	
Found 3/4" Iron Pipe 1.2 Found Northwest Corner		r stone	S50°E	121.75 feet			3		NO.)104		
Found 6" Maple	_		S30°E	91.60 feet (no	w 12")	`	No. of	900	********	SULTER	7
Found Nail & Tag Souths Found Nail & Tag Top Ce			N80°E N20°E	15.04 feet 41.52 feet			· CO	WHES	SION	I FILE LAND	
•					- ***		- entit	minim	mmmm,	W.	
C. Description of monume Set Remonumentation Cor	ent for corner a	nd accessories e	stablished to per	petuate locating the	position	of the ک	ALTONIA	ΎSιτ)⊦	WICH/C	O MARINE	
Set Remonumentation Col Set Nail & Tag Northside		micht DOX.	S85°E	32.56 feet		THE STATE OF THE S	* .*	,••• WIL:⊥i			
Set Nail & Tag Westside	Maple 26"	II Daak HOA SOT	S15°E	123.67 feet 15.04 feet				TING	•	ا ع:	
Found Nail & Tag Souths Found Nail & Tag Top Co	side Guard Ka enter Guard R	ail Post #21567	N80°E N20°E	41.52 feet		THE TOTAL		PACFE: SURV	i i	ر بر بر	
Northwest Corner Garag			S50°E	121.75 feet 91.6 feet		THE RES	ξ.·.	л 30	٠.,	· A	#
Centerline Maple 12"			S30°E	•		. 1	P	OFES	CIUNE,	SHIRING	
This corner is accepted as	a careful and	i faithful perpetu		e //	i corne	۲.		-LES	2101	Allika"	
Signed by Weller	n line	(ay	Da	ite Maj		994					

Surveyor's Michigan License No.

LI8ER

June 1973

Found stone

3/4" pipe set over stone

Bottle Cap in Power Pole and Telephone Pole

Northwest Corner of garage

S60°E S50°E 32.40 feet

Center Silver Maple 6"

S30°E

121.75 feet 91.60 feet

June 1974, David B. Whittier, #10070, LCRC, Liber 1, Page 171

3/4" Pipe

East to South Guard Rail Post

14.7 feet

East Southeast to Nail and Bottle Cap Power Pole

32.4 feet

Guard Rail Post

N30°E

41.8 feet

October 1990, Jan S. Fokens, #21567, LCRC, Liber 2, Page 220

Found Pole Barn Spike on pavement Centerline of Croswell & Filmore Roads. Did not find 3/4" Pipe as called for.

Set Pole Barn Spike

Nail & Tag #21567 in South Fence 6 x 6 Post Railroad spike in North Face Power Pole

N85°E

15.60 feet 31.65 feet

Nail and Tag #21567 in top of 6 x 6 post

S85°E N15°E

44.72 feet

Yield Sign Post

S80°W

53.53 feet