: <del>∀</del>	, ,			:						
SURVE			v							
REMONUMEN			NTY REMONUMENTA		RAM	r <b>538</b> pai	ar 51	1		
AUG 3 1 19	9 Corner ap	proved by Peer	Group on 5	1 ce 5		1994				
_		LAND COR	NER RECORDATION (	CERTIFICATI	<b>E</b>	. ~ .				
COMMIS	SION	Filing Requ	irement of Act 74, Mic	ch. P.A. 1970		· · · · · · · · · · · · · · · · · · ·				
For corners in					Crahot Co. Mich.					
Gratiot (County)		Located In: Corner Code #			RECORDED					
, ,					'94 AUG	19 AM 1	0 09			
1. Public Land Survey		10R_3	M-2, E 1/4	-						
	τ_ τ	R R		1	Jan	tm.D	con	£.		
		R			U RE	uis fer up deeds	I .	•		
Property Controlling     in Section		R R		-   _		1. 01 6	ru - M		_	
3. Miscellaneous		R	- 1 Mediate of Decas Statis a trio manifest							
Property in Sec.	ST_	R		_						
					, А В	C D E F G	<b>∍</b> H I	J K	L M	
5. Private Claims					2 6	5 4	3	.2	).	
					3				•	
I, William Tingl	ey	a field	survey onAugust ]	1994	4 7	8 9	10	-11	12	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					6 18	- 17 16	-15	14	13	
in lines 1 and 2 above w	ere in conforma	ance with regulation	is and rules therefore as re epartment of the Interior, Bu	equired in the	7	"   "	<u> </u>			
Management or by a decre	e of a Court of I	Law and/or that the	corner points mentioned in lib pard of Land Surveyors or by	nes 3, 4 and 5	8 19	20 21	22	23	24	
Court of Law; establish expressed below:	ed, re-establis	shed, monumented,	re-monumented, recovered	ed, found as	9	29 28	27	26	25	
·					11	ļ				
NOTE: Not more than on this certific		I in the same tow	n and range, may be rec	oraea	12 31	32 33	34	35	36	
A. Description of original	nat monument	and accessories	and/or subsequent restora	ation:	13	<u> </u>		·		
May 1831, R. Clark, Jr.			gitalor oubooquorit roto.c							
Set post Elm 14" S12	°W 23	links								
Sp. Oak 30" N66 May, 1871, D.W. Attent		links Surveyor Liber F	t Page 57							
Stone 8" x 8"			, rage or							
Stone S55°W Stone N57-1/2°V		links -1/2 links								
Old 1/4 Corner Four		South of W 1/4 6	-10-2							
Field Book, Gratiot Co  Stone 8 x 8	unty 10-3									
Stone S55°W Stone N57-1/2°		links 3-1/2 links								
Gratiot County Record	ls, 1-10-3, Re	cord of Minutes o	f Survey in Gratiot Coun	ty Road Com	mission					
July 1974, David B. W			1/2 links South of W 1/4 Page 181	Corner 6-10-2	2					
Found Rod in Mon B North Mon Box to B										
Nail & Tag Northea	st side Telepi		hwest 42.65 feet							
West to Centerline  B. Description of corr		12.65 feet ound and/or metho	d applied in restoring or re	eestablishing o	orner:					
Found 1" Iron Pipe in Below Iron Pipe four		nted Stone								
Top of Stone is 2.3 f	eet deep	med Otoric								
Accepted stone as C	orner					THE OF	MINIMUM MIO:	Wee.		
C. Description of mor	nument for cor	ner and accessorie	es established to perpetua	ate locating the	position of	the Corper Ur	UHIG	V MININE		
Found Nail and Tag	in Power Poi	A.CFN €	v 42.35 reet		4	A AAILLI	AIVI G.	* *		
Found Nail and Tag Set Nail and Tag in F		wer Pole S45°E S30°V				TING PROFE	SSIONAL	O.H		
Light Gauge Railroa W 1/4 Corner (1" Iro	ad Rail	N85°E	28.42 feet		Ī	SUR N	10. 10.	J. E.		
•	-	-			- t	THE PARTY	104	- SULFRIEN		
This corner is accepte		and faithful per	petuation of the position	of the origina 5 A cos	ai corner.	TINC PROFES	HERRICH IN	differ		
Signed by L.L.V.V.	an 1	しんしん とんしん	Daie		, <u>19</u> 94					

LIBER 3 PAGE 23

Surveyor's Michigan License No. \_