1993

COMMISSION

For

G

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

GRATIOT CO. MICH. RECORDED

•				
'93 DEC	20	PM	12	24

corners in	<u> </u>	Located In:	Corner Code #	LOGIAM
(County)				
	~			
Public Land Survey	Sec 2	T_10R_4	K-1, NE corner	

net M. Do REGISTER OF DEEDS

2. Property Controlling R R Register of Deeds Stamp & File Number S Т in Section 3. Miscellaneous

, Recorded Plat 4. Lot No. 5. Private Claims a field survey on William Tingley do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

December 6, 1831 Orange Risdon, Deputy Surveyor

Intersected North boundary 4 chains 61 links West of Quarter Section Post.

Set post corner sections 1 and 2.

Sugar Maple 14" S44°W 6 links

Sugar Maple 18" S64°E 32 links

April 20 and 21, 1880 Thomas H. Harrod, Deputy County Surveyor, Book C page 43in Record of Minutes of Survey in Gratiot County **Drain Commission**

Old Corner Found 2 x 2 Oak Post, stone on top

Apple 10" S44-1/2°E 77-1/4 links

Corner of Large Stone S41°E 30 links

November 7, 8, 9, 1881 D.W. Altenburg, County Surveyor, Book C page 77, in Record of Minutes of Survey at Gratiot County Drain Commission.

Old corner found, Stone and small stones by side

Elm 10" N55°W 1.19 chains

Apple tree 6" S54°E 64.5 links

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron in monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set remonumentation corner and monument box.

Nail and tag Westside Power Pole, S45°E, 37.3°

Nail and tag Northwest side Power Pole, N40°E, 48.5

Nail and tag Eastside Power Pole, N20°W, 145.65

S 1/4 corner 36-11-4, East, 304.26.

Corner is 1.5' south of centerline.

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

William G. 是你的特性是 PHEGICATION MEADS NO. 26104 TO LATE OF

Surveyor's Michigan License No.

November 30, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

LIBER