SURVEY & REMONUMENTATION

AUG 3 1 1994

COMMISSION

GRATIOT COUNTY REMONUMENTATION PROGRAM LIBER 538 PAGE 509

Corner approved by Peer Group on _____, 1994

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

GRATIOT CO. MICH.
RECORDED

'94 AUG 19 AM 10 09

Janet M. Davis
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in Gratiot (County)

		Located In:		Corner Code #
1. Public Land Survey	Sec 8	T 11	R 3	D-5, S 1/4
		T	R	
		T	R	
		T	R	
2. Property Controlling	S	T	R	
in Section	S	T	R	
3. Miscellaneous	S	T	R	
Property in Sec.	S	T	R	

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on August 2, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

May 19, 1832, Hiram Burnham, Deputy Surveyor, GLO Notes
Set Post
Beech 10" N24°W 26 links
White Ash 10" S24°E 4 links
February 1879, D.W. Attenberg, County Surveyor, Liber B Page 283
Post 3 x 3
Pine Stump 36" N56°W 59 links
Beech 10" S33°W 59 links
October, 1888, Parker Merrill, County Surveyor, Liber C Page 162
Stone
January 1906, E.W. Redman, County Surveyor, Liber D, Page 66
Pine Root, Stone and Iron around
Oak Tree N70°18W 1.17-3/4 chains (evidence of old wtiness stump to Northwest found)
Monkey Wrench and plow wheel over it South 33-3/4 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" Iron Pipe 1.6 feet long in Mon Box
At 2.3 feet deep found 3/4" Iron Pipe 2.0' long
Found Nail Eastside 14" Walnut South 47.13 feet
Found Nail Northeast side Power Pole N65°W 119.06 feet
Found Nail East side Power Pole N20°W 106.05 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remonumentation Corner and Monument Box over 3/4" pipe
Found Nail Eastside 14" Walnut South 47.13 feet
Found Nail Northeast side Power Pole N65°W 119.06 feet
Found Nail Eastside Power Pole N20°W 106.05 feet
Set Nail & Tag 4" Apple N50°E 51.85 feet

STATE OF MICHIGAN
WILLIAM G. TINGLEY
PROFESSIONAL SURVEYOR
NO. 30104
LICENSED PROFESSIONAL SURVEYOR

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William Tingley Date 5 Aug, 1994

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

ACCEPTED BY THE GRATIOT COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD_____

William Tingley

William Tingley, PS, Chairman