LIBER 551 PAGE 1002

GRATIOT CO. MICH.
RECORDED

'95 DEC 20 PM 1 28

Janet M. Davis
REGISTER OF DEEDS

GRATIOT COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Gratiot (County)

		Located In:	Corner Code #
		Sumner Township	
1. Public Land Survey	Sec 8	T 11 N R 4 W	D-5, 1/4 Corner
		T___ R___	
		T___ R___	
		T___ R___	
2. Property Controlling	S___	T___ R___	
in Section	S___	T___ R___	
3. Miscellaneous	S___	T___ R___	
Property in Sec.	S___	T___ R___	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, William Tingley a field survey on October 3, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1832, Orange Risdon, Deputy Surveyor, GLO Notes
Set quarter section post
Elm 14" N27°W 7 links
Sp. Oak 12" S48°E 56 links
1876, D.W. Altenburg, County Surveyor, Liber B, page 232, Gratiot County Drain Commissioner's Office
Old 1/4 Found
Ash Post 3" x 3"
S. Oak 10" S82-1/2"E 31-1/2 links
S. Oak 9" S59°W 29 links
November 1876, D.W. Altenburg, County Surveyor, Field Book 11-4, Pages 100-101
Root (notch cut in log for same)
S. Oak 18" S82-1/2°E 31-1/2 links
March 19, 1974, David B. Whittier, LCRC, Liber 1, Page 245
Found 1-1/4" pipe with 3" Cedar Point at North side; North to centerline 2" Round Iron Post, 25.5 feet;
ENE to Nail & Flag Southside 12" Stump 87.22 feet
Southeast to Nail & Flag Northeast side 14" Stump 49.0 feet
1992 Gratiot County Road Commission
Found 1-1/2" pipe with old Oak stake and 5" stone
Found root with 12" diameter notch in East side
Spike in 5" Swamp Oak N30°W 45.30 feet
Spike in 5" Ash Tree N40°E 99.60 feet

ACCEPTED BY THE GRATIOT COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD 11-29-95

WGT
William Tingley, PS, Chairman

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Centerline East-West pavement (Harrison Road) found 3/4" over 1-1/2" iron pipe and old stake and log with notch.
Found 5" Ash N40°E 99.60 feet

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Remonumentation Corner over 3/4" pipe in Monumentation Box
Set Nail and Tag in Westside 6" Aspen N45°W 56.20 feet
Set Nail and Tag in Eastside 5" White Oak N10°E 99.75 feet
Set Nail and Tag in Eastside 6" Ash N40°E 99.75 feet
Set Nail and Tag in 2" Aspen N30°E 63.80 feet

WILLIAM G. TINGLEY PROFESSIONAL SURVEYOR NO. 30104 LICENSED PROFESSIONAL SURVEYOR

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William G Tingley Date 12-12, 1995

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

REMONUMENTATION

FEB 2 2 1996

COMMISSION

LIBER 3 PAGE 55