## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 25 N.R. 9 W

			<del>-</del>	GRAND	TRAVERSE	COUNTY
DESCRIPTION OF CORNER	M.C. common	to Sections	13 & 14 on S	Side of	Helen Is.	in Fife Lake
CORNER MONUMENT	Fd. 14" old	rusty pipe a	t edge of wa	ter in b	rush.	
DATE MONUMENT PLACED	AND WITNESSED _	3/29/69				
WITNESSES TO CORNER		Set 5" sq	uare top Ced	r guard	post	
M.C.	<del></del>	10" Tam.		1 31 W		51.4'
13		8" Tam.		1 24 E		66.8'
CIRCLE CORNER REGISTER	AND					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered during retracement survey in this area. The corner fits witness and data by B. E. Teed, U.S. Deputy Surveyor, dated May 5, 1903.

For additional info see PLAT OF SURVEY.

SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR 12028 DATE ###### 5/29/69