LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 11 W.	D-11; E-11
2. PROPERTY CONTROLLING IN SECTION 29	,T. 25 N., R. 11 W.	7; 14; 16
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on October 15, 19 73, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__ , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. ~~Description of original monument and accessories and/or subsequent monument~~

C. (CONTINUED)

14

Set 1¼x54" pipe & cedar post
w/location tag

6" B. Cherry	N61°W	5.5
8" W. Birch	N27°E	22.2
9" W. Birch	S39°E	18.2

All witnesses in shallow flood area.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-11 Recovered 3/4" pipe by old corner fence post, fence E-W-S, per E. P. Waterman Survey of Record (1911).

E-11 Found 1½" well point per E. P. Waterman Survey of Record (1911).

7 Established corner by single proportion. Pipe on skew over cedar stump (cut-cross in stump).

14 Established corner by single proportion.

16 Found buggy axle by corner fence post, fence S & E, per E. P. Waterman Survey or Record (1911).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-11

Found 3/4" pipe, added DNR mon.
NO WITNESSES AVAILABLE

16

Found axle, added 1¼"x18" pipe

14" Maple	S24°E	38.1
10" Maple	S73°E	79.0
20" Maple	N83°E	15.0

E-11

Found well point, added DNR mon. and cedar post

6" Spruce	N61°W	76.6
9" Maple	S43°W	4.2
6" Maple	N64°E	46.5

on random west & north & east

7

Set 1¼x54" pipe & cedar post
w/location tag

14" Cedar	S30°W	4.7
8" Cedar	N45°W	9.4
8" Cedar	S85°W	23.0

west bank of Anderson Creek
east 10'±

SIGNED BY Carl F. Roser DATE 7-3-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR
(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

MAYFIELD TWP.

GRAND TRAVERSE COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM736
Lithographed by Dawson & Co., Kalamazoo, Mich.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS