LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 11 W.	H-11; I-9; I-11
2. PROPERTY CONTROLLING IN SECTION 27	T. 25 N., R. 11 W.	16
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on May 1, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument and accessories and/or subsequent restoration:~~

C. (continued)

16

Set 1"x36" pipe & cedar post w/location tag

6" Maple Clstr.	N59°E	25.6
9" Maple	N27°W	56.6
8" Maple Clster.	S51°W	26.3
E-W fence remains	Due S	4'
Irregular fence	N. Due E	22'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

H-11 Restored corner. Position of this corner fits stream crossing tie in U.S. notes, 4.03 Ch.E. to nearest 10 links. No other corner position would fit this, and the distance ½ mile west of 2621' per old survey of rec., Liber 1, page 122, 1899±.

I-9 Recovered ½" rod, per E. P. Waterman surveys, L. 2, page 324, 1908 & L. 5, page 221, 1903.

I-11 Restored corner on average line of fence remains N-S-W (mostly down) and 33'± south of fence remains to east. This fits a computed position by double proportion within 3'±. Also see survey of Section 27, Liber 1, page 122, 1899±.

16 Established corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-11

Set DNR monument & cedar post

12" B. Cherry	S45°E	32.1
9" Cedar	N45°W	61.8
7" Maple	N42°E	18.2
14" Cedar stub (5-foot high)	N85°W	32.7
Irreg. E-W BW fence	Due S	11'

I-9

Found ½"x3' rod w/sq. head, add. 1"x36" pipe

28" W. Pine	S44°E	35.20
17" W. Pine	S32°W	85.75
P. Pole	N18°E	81.65
Set cedar post	Due N	33'
Center E-W gravel rd.	Due S	7'

I-11

Set DNR monument & cedar post

12" B. Cherry	N30°E	3.3
8" Cedar	S19°W	80.3
40" W. Pine stump remains	S64°W	15.4

SIGNED BY Carl F. Roser DATE 7-3-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____

MAYFIELD TWP.
GRAND TRAVERSE COUNTY.

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM736 KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS