## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



## LAND CORNER RECORD

T. 25 M.R. 12 W

4 corner	common	to Sooti				
	1/4 corner common to Sections 19 and 20					
Drove la x 24 pipe, only						
TNESSED _	L	F 6 6		<del></del>		
····			<del> </del>			
	J'm B	l. Oak	N 74 E	39.1		<del>_</del>
	24 <b>а</b> н	i. Maple	S 63 W	14.5		
D						
	TRESSED _	Lu F	ha R. Oak  24 H. Maple	Lu R. Oak N 7h E  2h H. Maple S 63 W	1 R. Oak N 7 LE 39.1 24 H. Maple S 63 W 14.5	14 R. Oak N 74 E 39.1  24 H. Maple S 63 W 14.5

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners while making a survey of Section 20. No evidence of a previous corner or USBTs.

SURVEYOR'S SEAL

SIGNED Limith Solveyor #10068 DATE April 21, 1966