LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25 N., R. 12 W.	A-7; D-7; D-8
2. PROPERTY CONTROLLING IN SECTION 20	,T. 25 N., R. 12 W.	3
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 24, 19 79, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

~~A. Description of original monument, and accessories, and/or subsequent restoration~~

C. (continued)

3

Drove 5/8"x3' rerod w/RLS Cap & Cedar Post w/Loc. Tag.

6" Maple	S72°W	23.3
12" Oak	N23°E	4.6
9" Oak	S45°E	10.0

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-7 Restored sec. cor. common to Sec. 18 & 19 (25-12) & Sec. 13 & 24 (25-13) per USBT (16" w. pine stump) S77°W 10.6'. Corner falls in roots of pine stump (US calls for cor. tree) & fits Allyn 1904 sur. of Sec. 18 (L-3, p. 308 & 309) & Waterman 1909 road sur. (L-2, p. 554). W line of Sec. 18 for ½ mile N is 33'± W of E'ly road r-o-w fence remains.

D-7 Fd. Dept. mon. for N¼ cor. of Sec. 20 as set by RLS K.J.Ostling (dept. sur. 1966) from USBT stump NE showing good lower face.

D-8 Established center of Sec. 20 at intersection of ¼ lines. Corner falls 8'± S of wire in trees to E and 9'± E of wire on ground to S.

3 Set 1/8 corner per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7

Set DNR Mon. & Cedar Post.

14" Cherry	N50°E	50.20
Cherry Clump	N75°W	62.90
18" W. Oak	S64°W	224.53
Ctr. sand rd. (looking N)		
	Due E	6'±

D-8

Drove 5/8"x3' rerod w/RLS Cap & Cedar Post w/loc. tag.

12" Twn.Maple	N05°E	15.0
6" Maple	S71°W	32.9
8" Maple	S15°E	21.4

D-7

Fd. DNR Mon.; added ced. post. KJO Wit - 24" W. Pine Stp.

	S74°E	8.1
6" Oak	N44°W	40.3
4" Maple Clstr.of 3-	S20°W	13.79
4" Oak	S72°W	48.1
E-W Trl. Rd.	North	118'±
E-W Random	North	15'

SIGNED BY Carl F. Roser 4-8-80 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

GRAND TRAVERSE COUNTY
GRANT TOWNSHIP

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET