## **SURVEY &** REMONUMENTATION

JUN 0 1 1998

| •  |   | •   |  |   |   |  |  |
|--|---|---|--|---|---|--|--|
| SECTION  | LAND CORNE  | ER RECORDATION CER  | RTIFICATE  |   |   |  |  |
| For corners in   | Filing Require  | ement of Act 74, Mich.  | P.A. 1970  | SURV<br>REMONUM   |   | NI   |  |
| Grand Traverse   | Logotod Inc   | 0. 0.14   | ;<br>;   | IEMIONON  | ICIVIALIO   | 1.4  |  |
| (County)   | Located In:   | Corner Code #   |  | JUN 0   | 1 1998  |  |  |
| 1. Public Land Survey  | T <u>- 277N</u> R <u>- 9W </u><br>T R<br>T R  | # 13 M-01   |  | SECTION   |   |  |  |
| 9 Proporty Controlling C   | T R   | -   |  |   |   |  |  |
|  | T R<br>T R  |   |  |   |   |  |  |
|  | T R   | 778-4-1-  | Registe  | Register of Deeds Stamp & File Number                                       |   |  |  |
| Property in Sec. S _   | T R   |   |  |   |   |  |  |
| 4. Lot No, Record  | ed Plat   |   |  |   |   |  |  |
| 5. Private Claims  |   |   |  | A B C D E   | FGHI  | JKŁ  |  |
|  |   | ,   | 2  | 1 1 1 1 1 T   | ╌╡┈┼╾╡╌┼  | -2   |  |
|  |   |   | 3  |   | <del>                                     </del>              | <del></del>                                |  |
| , Robert F. Mitchell , in a  | field survey onNover  | mber , 19 93  | 3 5  |   | -9-10-1   | -1112-                                     |  |
| do hereby certify that under requireme in lines 1 and 2 above were in confo  | ints of P.A. 74, Michigan P.A.  | of 1970, the corner points mer  | ntioned  | 18 17   | 1615  | -1413-                                     |  |
| current manual of survey instructions  | of the United States Depart   | lment of the Interior, Bureau   | of Land 7  |   |   |  |  |
| Management or by a decree of a Court<br>above were in conformance with the re  |   |   | ree of a   | 1,0   | 21 22   | -2324-                                     |  |
| Court of Law; established, re-established  |   |   | und as   |   |   |  |  |
| expressed below: NOTE: Not more than 4 corners   | all in the came town as   | nd range moute records  | 10<br>d 11   | 1 2   | -28 - 27  | -26- 25-<br>                               |  |
| on this certificate.   | , an in the same town an  | id range, may be recorde  | iu<br>12   |   | 32 34   | 76 76                                      |  |
| A. Description of original monum   |   |   | 13   |   | "   | 30   |  |
| M-13; Corner of Towns 26N and 5L," U.S. Survey by Alvin Burt DNR surveyor, dated around 193 by Jerry L. Wilcox, dated 1-15 "Found Corner recorded in Libe flanged bottom galvanized iron surface of the ground," a Land of the Kalkaska County Land Corner recorded in Libe flanged bottom galvanized iron surface of the ground," a Land of the Kalkaska County Land Corner recorded in Libe flanged bottom galvanized iron surface of the ground, "a Land Corner recorded in Libe flanged bottom galvanized iron surface of the ground," a Land Corner recorded in Libe flanged bottom galvanized iron surface of the ground Land Corner recorded in Libe flanged bottom galvanized iron surface of the ground land land land land land land land la | t, deputy surveyor, da<br>30. "Found iron in cer<br>5-73, and recorded in<br>ar 1, Page 171 of the<br>n pipe with 3½" brass<br>d Corner Record by Mic | ated April 12, 1839. 'nterline of trails Nord<br>Liber 1, Page 171 of<br>Land Corner Records F<br>cap stamped CRAND TRA | "Original Conth, Fath, South, Fathe Land Contact County Release County RVERSE COUNTY | ner," survey<br>st and West,<br>mer Records<br>ty and replac<br>REMONIMENIA | index by M. 'Land Corner of Kalkaska ed with a 2 TION, 12" be | Schaaf,<br>r Record<br>County.<br>2" x 30" |  |
| 8. Description of corner evidence M-13: Corner of Towns 26N and recorded in Liber 3, Page 25 of perpetuation of the position of cap stamped GRAND TRAVERSE COUNTY 25 of the Kalkaska County Land   | d 27N and Ranges 8W at<br>of the Land Corners Re<br>of the original corner<br>VIY REMONUMENTATION, W  | nd 9W; Found 3" iron p<br>cords of Kalkaska Count<br>and a 2½" x 30" flange   | oipe in a fount<br>ty, and is acceded bottom gal                                     | r-way trail n<br>cepted as a c<br>vanized iron                              | eareful and a<br>pipe with 3                                  | faithful<br>k" brass                       |  |
|  |   |   |  |   |   |  |  |
| •  |   |   |  |   |   |  |  |
|  |   | •   |  |   |   |  |  |
|  |   | ·.  |  |   |   |  |  |
|  |   |   |  |   |   |  |  |
| C. Description of monument for M-13; Corner of Towns 26N and 2 2½" x 30" flanged bottom galva below the surface of a four-way  | 7N and Ranges 8W and 9<br>enized iron pipe with   | 9W;<br>3½" brass cap stamped  |  |   | EMONUMENTATI  | -  |  |
| N23°E - 12" White Oak - 53.18'   |   |   | •  | A A   | E OF MICH   | 24   |  |
| S45°E - 4" Red Pine - 43.121   |   |   |  | 101   | ROBERT F.   | <b>I</b> ,"/                               |  |
| S37°W - 10" Red Pine - 63.581  |   |   |  | # * I   | MITCHELL  | 1 * §                                      |  |
| N60°W - 7" Red Pine - 40.71'   |   |   |  |   | ROFESSIONAL<br>SURVEYOR                                       | 5  |  |

Corner approved by the Grand Traverse County Peer Review Group on 12-15-93.

28417

Signed by ..

Surveyor's Michigan License No. .

December 28, 1993