STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		GUMIN INVALUE COUNTY	
		T	R <u>9 ₩</u>
DESCRIPTION OF CORNER	Ctr. corner Section 35		
CORNER MONUMENT	Fd. Blue Pointed Stone Added 1'x34' Pipe (bur	on End surrounded	by smaller stones
DATE MONUMENT PLACED AND			
VITNESSES TO CORNER	Ctr. L-W Co. koad	Due S.	31
N	Old Cor. Fn Post	Due N.	291
	18 Maple	S 44 W	47.55
3 5	AND 24" Haple	S 30 L	35.73
CIRCLE CORNER REGISTER	ÆD		- <u> </u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey in this area. Found above-described stone in line with old fence remains to N & S. L. P. Waterman survey of Sec. 35 in Sept. 1893, as recorded in County Survey Records at Register of Deeds in Liber 1, P-420, calls for Cedar Post & stones. Corner fits the 1893 Sec. Subdivision and is accepted as proper center of Section.

SURVEYOR'S SEAL

SIGNED

Cal J. Hoxer

8-5-70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 12028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing