

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 26 N. R. 9 W.


Grand Traverse COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 21-22-27-28

CORNER MONUMENT Left 1 $\frac{1}{4}$ " pipe with concrete base in place.

DATE MONUMENT PLACED AND WITNESSED 11/3/61

WITNESSES TO CORNER.....



6" W. Oak - N43W - 41.2 feet

9" W. Oak - S49W - 45.4 feet

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a corner search in this area. Found 1 $\frac{1}{4}$ " pipe with concrete base in centerline intersection of fireline roads N-S-E-W, as established by Marcus Schaaf, R.L.S., in 1935 survey.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Ostling* DATE 11/13/61
REGISTERED LAND SURVEYOR