

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

GRAND TRAVERSE COUNTY


T 26 N R 10 W

DESCRIPTION OF CORNER Sec. corner common to Sections 27-28-33-34

CORNER MONUMENT Found 3/4" Pipe

DATE MONUMENT PLACED AND WITNESSED 5-27-69

WITNESSES TO CORNER..... Set 4" sq. top Cedar Post with location tag, So. 33'



10" Elm N 23 W 62.1'

10" Elm S 54 W 34.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a tetracement survey in this area.

The corner is at the approximate position of the Centerline trail road S.,  
centerline blacktop County Road E-W, and Centerline Hedge Row North.

SURVEYOR'S SEAL

SIGNED

*Carl F. Roeder*  
REGISTERED LAND SURVEYOR

DATE

6-3-69

DISTRIBUTION:

12028

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68