

LIBER 1103 11.722

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in Gra nd	Traverse	Located In:	Corner Code =##	1		٤	TATE	OF N	ICHI	GAN			
	(Cou	nly)		F-1 ·	l l		GRA	IT ON	RAVER	SE C	DUNT	Y		
1.	Public Land	Survey	7 26N 11W T R		٠				RECOR	DED	; ;;	.•		
2.	Property Go	ontrolling	T R T R S T R	W0 L					y A No	DER!	30N ·		هر	
	In Section		S T R	TT-11-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1				INCUL	i) I Info	OL Y	/L LLEA	e.		
3.	Miscellaneo	ous	S T R		Red	gister o	f De	erie S	tamı	n R F	-ile i	dum.	her	ı
	Property in	Sec.	S T R									10111		
4 . 5.	Lot No	, Re	ecorded Plat			· A_	в с	: D	E F	6_	н	.	к	L M
U .						2	-	- <u> </u> - 5	-4-	- -	3	<u>}</u>	-	- -
						3	\vdash				-	\dashv		-
	Garth (). Stowe	Oc	tober 90	6	4 -	┆┼	8 	-		ф <u>-</u> -	1		_ 2
1,, in a field survey on, 19, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the								- -	16	1	15	-14	_	__
			tions of the United States Depart			7├—	┝┯┝		╌┼	_ _	┼	┝╼┾	-	
			Court of Law and/or that the corne			81	.	-20	-21-		22—	23	-	2 ↓
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as								Ц	\sqcup		<u> </u>		_	
ex	pressed below	;	-established, inchallented, re-	monumented, recovered, i	iouna as	10	\perp				<u> </u>			25
NC)TE: Not mo	ore than 4 co	rners, all in the same town a	nd range may be record	led	11				\mathbb{I}^{-}	Ĺ	20		
		certificate.	an in the count term of	ra range, mor be record		12		72					Т	
						13	ï	-3 <i>e</i> -]	1	\neg	-36
A.	Description	of original m	onument and accessories an	d/or subsequent restoral	tion:						-			

- F-1: No available County Surveyor records. Batzer, in 1978, sets North 1/4 corner 19.4 feet West of South 1/4 corner of Section 33, T.27N. R.11W., treats as lost corner and sets equadistance from the Northeast and Northwest corners of Section 4, T.26N., R.11W. Certificates of Survey: by: Batzer in 1978, Wilcox in 1980 and Grush in 1991.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - F-1: Found 5/8" iron bar in monument box in centerline of Rennie School Road 19.4 feet West of South 1/4 corner of Section 33, T.27N., R.11W. Corner accepted as a locally accepted corner established by Batzer in 1978.

UNANIMOUSLY ACCEPTED BY THE GRAND TRAVERSE COUNTY PEER REVIEW GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC CT 345 OF 1990 AT ROBERT F. MITCHELL, P.S., Li IAIHMAN

-C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

F-1: North 1/4 Corner, Section 4, T26N, R11W Set monument box with 2-1/2" x 30" flanged bottom galvanized pipe with 3-1/4" brass cap stamped GRAND TRAVERSE COUNTY REMONUMENTATION in centerline of Rennie School Road. North 34.30 Power Pole

S42°E 106.65' Face of Well S18°W 87.40' 10" Maple S47°W 73.80' 5" Elm

Corner approved by the Grand Traverse County Peer Review Group on December Contrago

D. STOWE Date

LAND SURVEYOR

OF CARD STAYETORS TARE 20, 1971

ENTE LAND
HERSED JAN., 1983

Burveyor's Michigan License No. _

D. Stowe Garth

25875