SURVEY & REMONUMENTATION

LIBER 1103 FAST 770

APR 0 7 1998

LAND CORNER RECORDATION CERTIFICAT Filing Requirement of Act 74, Mich. P.A. 197	
For corners in SECTION	`
Grand Traverse Located In: Corner Code #	STATE OF MICHIGAN GRAND TRAVERSE COUNTY
1. Public Land Survey	RECORDED 31 DEC 97 252 P.H.
Z. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	KARON ANDERSON REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J K L 2 6 5 4 3 2 1
1, Garth Stowe , in a field survey on October , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	4 -7 8 -9 -10 -11 -12 5 -18 -17 -16 -15 -14 -13 7 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
	11
A. Description of original monument and accessories and/or subsequent restoration:	13
of 1/4 post in T27N R11W. Waterman, 1908, references 2 corners the west being the correcorner is iron stake and stone in place of old cedar post by Tuller. The east fence is the 1/4 Perla Stout Associates, 1967 find 1 1/2" I.P. Land comer by Korr find 1 1/2" iron pipe at S 1 1/2" iron pipe 10.31' west at N 1/4 corner section 3, T26N R11W. B. Description of comer evidence found and/or method applied in restoring or reestablishing content. N 1/4 corner section 3, T26N, R11W. H-1: N 1/4 corner section 3, T26N, R11W. Found 1 ½" iron pipe as noted in Land Corner Record above. This corner is accepted as a	post for section 34, T27N, R11W. 1/4 comer section 34, T27N, R11W notes priner:
Tuller corner of 1893 and is monumented with a 2 1/2"x30" flanged bottom galvanized pipe TRAVERSE COUNTY REMONUMENTATION.	
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
H-1: North 1/4 corner section 3 , T26N R11W Set 2 1/2"x30" flanged bottom galvanized pipe with a 3 1/4" brass cap stamped GRAND TREMONUMENTATION.	RAVERSE COUNTY
S 08° W 36.85' 3-14" Maples East 12.53' 8" Basswood D. STO N 25° W 7.11' 6" Basswood LAI S 85° W 42.06' 12" Basswood SURV	OWE * F
Comer approved by Grand Traverse County Peer Review Group 10-22-97	AND SUMMED TO THE PROPERTY OF
Signed by Date	12-19-97
Surveyor's Michigant License No. 25875 UNANIMOUSLY ACCEPTED BY THE	
PENER OF COUNTY PEER	GAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1976 REVISED JAN REVISED OCT

REVISED JAN, 1983 REVISED OCT, 1995