LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. _____ N. S., R. _____ E. W.	
2. PROPERTY CONTROLLING IN SECTION 13	T. 26 N. ●., R. 11 ●. W.	4; 8;
3. MISCELLANEOUS PROPERTY IN SECTION 13	T. 26 N. ●., R. 11 ●. W.	*657'-E OF #10,S-13

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on FEBRUARY 3, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on February 3, 1983, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED;

8

REFERENCE COR: DROVE 5/8" X 36" REROD W/RLS CAP
& SET CEDAR POST W/LOC TAG, N00°24'W, 60.00' FROM
CALC 1/8 COR POSITION IN RV.
WIT TO REF COR:
P. POLE N70°E 45.23
NE COR OF WOODEN BRIDGE N50°W 26.3
N. EDGE OF RV IS 20' SOUTH
S. EDGE OF RV IS 155' SOUTH

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

*657'-E OF #10,S-13 - FD 1" X 24" PIPE ON WET SPRINGY SIDE HILL FOR SE COR OF W 1/2 OF NW 1/4 OF SW 1/4 OF SEC 13; FITS OUR SEC SUBD OF SW 1/4 OF SEC 13. DROVE 5/8" X 36" REROD 0.5' DEEP & DROVE FD 1" PIPE OVER IT.

4 - DROVE 5/8" X 36" REROD FOR NE COR OF SW 1/4 OF NW 1/4 OF SEC 13 (CTR OF NW 1/4). COR FALLS 3'± EAST OF CTR OF N-S GRAVEL ROAD AND IS IN LINE WITH NEWER W-W FN ON CEDAR POST TO EAST.

8 - SE COR OF SW 1/4 OF NW 1/4 OF SEC 13; CALC POINT ONLY IN RIVER, NO POINT SET. DROVE 5/8" X 36" REROD, N00°24'W, 60.00' FROM CALC 1/8 COR IN RIVER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

*657'-E OF #10,S-13

FD 1" X 24" PIPE & SET CEDAR POST W/LOC TAG
8" MAPLE N10°E 4.9
6" MAPLE N70°E 19.2
3" MAPLE S50°E 9.2

4

DROVE 5/8" X 36" REROD W/RLS CAP
14" CHERRY N50°E 49.84
6" W. PINE S50°W 49.22
8" W. PINE S80°W 65.60
SET CEDAR POST W/LOC TAG WEST 33'

SIGNED BY Carl F. Roser 06/02/83 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

BLAIR TWP.
GRAND TRAVERSE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET