LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 26 N., R. 11 W.	K-8; K-9;
2. PROPERTY CONTROLLING IN SECTION 23	,T. 26 N., R. 11 W.	7
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER _____

I, CARL F. ROSER, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on FEBRUARY 3, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. CONTINUED

~~Description of original monument and accessories and/or subsequent restoration:~~

7

DROVE 5/8" X 36" REROD W/RLS CAP

5" OAK	N55°E	52.0
4" W. PINE	S65°E	65.4
4" W. PINE	N40°W	22.2
SET CEDAR POST W/LOC TAG	EAST	33'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-8 FD 1/2" ROD BY RLS, L. CZUBEK FOR E 1/4 COR OF SEC 23. FITS E.P. WATERMAN'S 1917 SURVEY VERY CLOSE. CORNER FALLS 4'± N. OF CTR OF GRAVEL RD WEST AND SE'LY IN CURVE.

K-9 FD 1 1/2" PIPE FOR SE COR OF SEC 23. A 2 1/2' LONG SHAFT WITH 6" DIA GEAR ON TOP IS 0.7' EAST OF 1 1/2" PIPE, AN OLD OVERGROWN, WET, SWAMPY ROAD GRADE INTERSECTION E-W-S IS 18'±N AND 9'±W.

7 - DROVE 5/8" X 36" REROD FOR NE COR OF SE 1/4 OF NE 1/4 OF SEC 23. COR FALLS IN WINDING TRAIL ROAD.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-8

FD 1/2" ROD W/RLS CAP #12581

6" W. PINE	S10°E	21.27
8" W. PINE	S30°W	32.73
11" MAPLE	N54°W	14.38
SET CEDAR POST W/LOC TAG	SOUTH	33'

K-9

FD 1 1/2" PIPE; ADDED CEDAR POST W/LOC TAG

8" CEDAR	N40°E	9.8
9" CEDAR	N88°E	15.8
8" CEDAR	S60°W	17.1

SIGNED BY Carl F. Roser 06/02/83 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

BLAIR TWP.
GRAND TRAVERSE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET