SURVEY & REMONUMENTATION

APR 2 7 1995

COMMISSION

		LIBER 003 PAGE 57	4	•		
	LAND CORN	IER RECORDATION CERTI	FICATE			
Green Lake Twp. For comers in		rement of Act 74, Mich. P.		STATE OF HICHIGAN GRAND TRAVERSE COUNTY		
GRand Traverse	Located In:	Corner Code ##		RECORDED		
Public Land Survey	т <u>26</u> N п <u>1</u> 2W	А-9		30 DEC 94 10:27 A.H.		
	T R T R T R			KARON ANDERSON REGISTER OF DEEDS		
2. Property Controlling in Section	S T R S T R	THE PARTY OF THE P				
Miscellaneous Property in Sec.	S T R S T R		Register of	Register of Deeds Stamp & File Number		
4 Lot No. Bu	ecorded Plat					
5. Private Claims	300700077101			CDEFGHIJK		
			3 3			
0 1. 1) 1	•		4	9 10 11		
do hereby certify that under requ	in a field survey on NOVE	ember 12 19 94 A. of 1970, the corner points mention	···•			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land				- - 7- - 6- - 5- - 4-		
Management or by a decree of a	Court of Law and/or that the corr	ner points mentioned in lines 3, 4 a	ind 5 8			
		fol Land Surveyors or by a Decree -monumented, recovered, found				
	GCA.#94420.01		10 _30-	- -29- -28- -27- -26-		
NOTE: Not more than 4 co	orners, all in the same town	and range, may be recorded	11	32 33 34 35		
			13			
A. Description of original n <u>A-9 West Corner common to Se</u> April 18, 1839 - U.S. Survey	ections 19 and 30	nd/or subsequent restoration: /2 - Wilcox & Erickson		2 - D.G. Heydlauff		
Set Post			Act 74 - L.3,	Act 74 - L.3, P.358V Found 3/4" Iron Pipe		
N59°W 28 lks - Hendock 24"	N59"W 28 lks - Hendock 24" S35"W 61.90' - Pwr Pole		S46°E 55.46	S46°E 55.46' - Pwr Pole		
N29"E 25 lks - Pine 22"	\$63°E 15 lks - Heech 13" N47°W 44.91° - Pwr Pole N29°E 25 lks - Pine 22" \$50°E 55.55° - Pwr Pole		N41°W 44.9	S51°W 67.93' - Pwr Pole N41°W 44.93' - Pwr Pole		
			N14°W 98.7	5' - SE Cor Blk Gar.		
				•		
•		applied in restoring or reesta	ablishing corner:			
Δ-2 West Cornet common to Se Found 5/8" carriage bolt with 1 14" down next to large granite s	" square head 3.84' West of 3/4" Iron F	Pipe, also found 1-1/4" seamed Iron Pipe				
Replaced Corner with a 2-1/2"x stamped "Grand Traverse Coun	30" flanged bottom galvanized pipe wi ity Remonumentation".	ith a 3-1/2" brass cap	UNANIMO	USLY ACCEPTED BY THE		
	oted as a careful reestablishment of the from 1839 to the present is uncertain.	original corner.	REVIEW (RAVERSE COUNTY PEER GROUP AS THE OFFICIAL UNDER MICHIGAN PUBLIC		
the perpetuitant of this come	non 1657 to the present is uncertain.		ACT 345	OF 1990 AT A MEETING ON 10-25-34		
			a.mo			
	١,			MITCHELL, P.S., CHAIHMAN		
		•				
C. Description of monumer	nt for corner and accessories	s established to perpetuate lo	cating the positio	n of the corner:		
A-9 West Corner common to Se	ections 19 and 30			ethod Charles		
	n galvanized pipe with a 3-1/2" brass ca	ap stamped "Grand Traverse	والمرابع والمرابع	CONTRACTOR		
N84"W 3.84" - 3/4" Iron Pipe	- Inc. system to see the total		>:			
836°E 53.50' - R Pine 14"			* *	Burney Jak		
N43"W 48.20' - Pwr Pole 850"W 77.27' - W. Pine 14"				Part of the state		
N15"W 100:60' - SE Cor Blk B	_			William Long		
Comer approved by Grand Travense	County Peer Review Group on 10-25	1994	7.7 No. 1	11 (16) see (1) 19		