## SURVEY & REMONUMENTATION

APR 2 7 1995

## COMMISSION

HER UO3 3F560

	•	THER GUS ARTOU	•
	LAND CORN	IER RECORDATION CERTI	FICATE
Green Lake Twp. For corners in	Filing Requi	rement of Act 74, Mich. P.	A. 1970 STATE OF MICHIGAN GRAND TRAVERSE COUNTY
Grand Traverse (County)	Located In:	Corner Code =##	RECORDED
Public Land Survey	T 26N R 12W	<u>A-10</u>	30 DEC 94 10:25 A.M.
	T R T R		KARON ANDERSON REGISTER OF DEEDS
2. Property Controlling in Section	S T R S T R	7011	
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds Stamp & File Numbe
4. Lot No , R	ecorded Plat		
I, Corey J. Hughes do hereby certify that under red	, in a field survey onDece	mber 7 , 19 94 A. of 1970, the corner points mention and rules therefore as required in	2 6 5 4 3 2 3 4 7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
current manuat of survey instru Management or by a decree of a above were in conformance wit Court of Law; established, r	ictions of the United States Depa a Court of Law and/or that the corn hithe rules of the Michigan Board e-established, monumented, re	or mes intererore as required in intiment of the Interior, Bureau of L ter points mentioned in lines 3, 4 at of Land Surveyors or by a Decree -monumented, recovered, found	and 7
	GCA.#94420.01 orners, all in the same town a	and range may be recorded	10 - 3029282726
on this certificate.	smors, an in the same town t	and tange, may be recorded	12 31 32 33 34 35
A. Description of original a \( \Lambda \)-10 West 1/4 Section 30 \( \text{U.S Survey} - \text{April 18, 1839} \) Set Post \( \text{S23"W 10 lks} - \text{Hemlock 10"} \) \( \text{N10"W 12 lks} - \text{Pinc 18"} \)	monument and accessories ar	nd/or subsequent restoration:	19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Early 1900's - C. P. Tutler Survey calls along West line of Sections 19, 30 & 31	г		
B. Description of corner e A-10 West 1/4 Section 30 Found RR spike not accepted	vidence found and/or method	applied in restoring or reesta	olishing corner:
of Section 31 and the fence line	e evidence at the S-1/8 and S-660' lines o	nce from the NW corner of Section 30 to of Section 30 support reestablishment of 0	2. P. Tuller.
Set at C.P. Tuller position a 2- County Remonumentation", in	1/2"x30" flanged bottom galvanized pip a pavement monument box.	e with a 3-1/2" brass cap stamped "Gran	Traversa UNANIMOUSLY ACCEPTED BY THE
The accessories and evidence for	ound are accepted as a enreful reestablis	shment of the original corner.	GRAND TRAVERSE COUNTY PEER REVIEW GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON \2
	s.	•	POBERT F. MITCHELL, P.S., CHAIHMAN
A-10 West 1/4 Section 30			ating the position of the corner;
County Remonumentation*, in N27°W 3.56' - RR spike	m galvanized pipe with a 3-1/2" brass ca a paveincel monument box.	p stamped "Grand Traverse	35 OF 1710 TELE
S87°W 36.98' - Power Pole S36°E 36.50' - Onk 12" N68°E 30.62' - W. Pine, triple	24"		COREV CORE
•	County Peer Review Group on 12-15-	1994	H CORFY J A TUGINES LAND SURVEYOR No.
	1	٠	20706