## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 26 NR 12 W

								COUNT
			Meander	Corner	common	to Sec	tions 5	sand bon
DESCRIPTION			of 1/4	corner.				
DESCRIPTION	OF	CORNER	MONUMEN	NT	_ 1"x24"	_ pipe		
WITNESSES "	то с	CORNER _	<b></b> -					
			Notch	in 20"	R. <b>6</b> ak -	<u>83</u> 6#	<u>T</u> 6	d links
			8" W.	Birch	- N5	7 A	- 1	Llinks

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a survey in this area. Set corner on the calculated true section line at its intersection with the flood line. Could make no identification of Oak government BTs.

Corner was placed and witnessed June 16, 1959.

SURVEYORS SEAL

SIGNED LIMITE JOSHUE DATE 6/29/59