

LIBER 003 PAGE 449

MAR 1 6 1994

4. Lot No. _

Private Claims _

LAND CORNER RECORDATION CERTIFICATE

for corners in COMMISSION	Filing Requi	rement of Act 74, Mich.	P.A. 1970
Grand Traverse	Located Inc	0	1

Located In:

_ , Recorded Plat _

STATE OF MICHIGAN GRAND TRAVERSE COUNTY RECORDED

δ****27 P.M. KARON ANDERSON

Corner Code ## T 27N R 9W 1. Public Land Survey REGISTER OF DEEDS 2. Property Controlling in Section Miscellaneous

Register of Deeds Stamp & File Number Property in Sec.

1. Robert F. Mitchell , in a field sur	rvey on	October	. 19 93
do hereby certify that under requirements of P.	A. 74, Michigan	P.A. of 1970, the cor	ner points mentioned
in lines 1 and 2 above were in conformance	with regulation	s and rules therelo	re as required in the
current manual of survey instructions of the U	Inited States De	epartment of the int	erior, Bureau of Land
Management or by a decree of a Court of Law a	nd/or that the c	orner points mentio	ned in lines 3, 4 and 5
above were in conformance with the rules of the	ne Michigan Boa	ard of Land Surveyo	ors or by a Decree of a
Court of Law; established, re-established,	monumented,	re-monumented, r	ecovered, found as
do hereby certify that under requirements of P. in lines 1 and 2 above were in conformance current manual of survey instructions of the U Management or by a decree of a Court of Lawa above were in conformance with the rules of the Court of Law; established, re-established, expressed below:	A. 74, Michigan with regulation Inited States De nd/or that the c ne Michigan Boa	P.A. of 1970, the cors and rules therefor epartment of the into orner points mentionard of Land Surveyor	rner points mentioned ore as required in the erior, Bureau of Land med in lines 3, 4 and 5 ors or by a Decree of a

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-2; 4 Cor. common to Secs. 2 & 3, T27N-R9W; "Beech post witnessed by Beech 14" N28°W 16 lks. and Beech 6" S23°E 49 1ks. U.S. Survey by Lucius Lyon dated May, 1850. "Found the old rotton Beech post at side of other post witnesses C.W. Cook, N.M. Glendinging, Edgar Pray, set pit of cobblestones 3' deep with a black hardhead granite 20" x 18" x 8" with an x on top and a quarter on the side," C.P. Tuller survey on May 23, 1892 recorded in Liber 1, Page 27 of the G.T. Co. Surveyors Records. "Found stone monument at the East & post with x on top," G. Steele survey of May 25, 1893 recorded in L.1, P.413 of the G.T. Co Surveyors Records. "Found a 2" x 8" x 12" stone lying half way down used high point," G.T. Co. Rd. Comm. survey of 1962. "Set ½" pipe with witnesses from Co. Rd. Engineer," William Downey "MDOT" survey of 1964. "Found iron," Land Corner by G. DelaMeter dated June 7, 1973 according to L.1, P.589 of Land Corner Records. "Found ½" iron pipe," certified boundary survey by William Batzer recorded in L.3, P.732. "Found a 20"x18"x8" black granite stone and pit of cobblestones as called (continued)

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(Continued Part "A") for by C.P. Tuller in his survey of 1892, corner is 24" below the road surface. Added ½"x18" rebar with cap #28417 and raised position of corner to surface. Also found a ½" iron pipe as called for by William Downey, an MOT surveyor, which bears N58°16'E, 7.85' from the true East ½ Corner," Land Corner Record by R.F. Mitchell recorded in L.3, P78 of the G.T. Co. Land Corner Records and dated 4-30-86. "Found 7/8" iron bar and a survey iron located S70°W, 7.84 feet," certified boundary survey recorded by Carth Stow recorded in L.7, P.218.

(Part "B")I-2; ½ Corner common to Sections 2 and 3 T27N-R9W; Found ½" x 18" iron bar with cap 28417 over a 18" x 12" x 8" upright, pointed, black granite stone that was next to a 20" x 6" x 20" flat upright gray stone with possible chisel markings on the side. There were several cobblestones surrounding both of these large stones. Corner is accepted as a careful and faithful perpetuation of the position of the original corner. This position was remonumented with a 2½" x 30" flanged bottom galvanized iron pipe with 3½" brass cap stamped GRAND TRAVERSE COUNTY REMONUMENTATION and placed 10" below the surface of the road.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-2; % Corner common to Sections 2 and 3, T27N-R9W;

2½" x 30" flanged bottom galvanized iron pipe with 3½" brass cap stamped GRAND TRAVERSE COUNTY REMONIMENTATION 10" below the surface of the road. OF MICHIG

N58°16'E - 7/8" iron rod - 7.85'

S50E - 8" Red Pine 51.15'

S20°E - 12" Red Pine - 66.48'

S58°W - 36" maple - 53.43'

S65°W - 24" maple - 66.70'

Corner approved by the Grand Traverse County Peer Review Group on 11-3-93.

ROBERT F. MITCHELL **PROFESSIONAL** SURVEYOR No. 28417 POFESSION

Sig	ıned	by	
-----	------	----	--