## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	ì	•		RECORDED
Grand Traverse (County)	Located In:	Corner Code	#	30 DEC 99 4:01 P.M.
1. Public Land Survey	T <u>27N_R_9\</u> TR	<u>W</u> <u>1-5</u>	-	KARON ANDERSON REGISTER OF IXEDS
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous Property in Sec.</li></ul>	S TR S	SURVEY & MONUMENTATION MAR 22 2000		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Plat			
5. Private Claims		SECTION		A B C D E F G H I J K L M  1
I, <u>Craig W. McVean</u> , in a field survey on <u>Oct. 7</u> , 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				8 -19 - 20 - 21 - 22 - 23 - 24 9 10 - 30 - 29 - 28 - 27 - 26 - 25
NOTE: Not more than 2 c this certificate.	orners, all in the same t	town and range, may be	e recorded on	11 - 31 - 32 - 33 - 34 - 35 - 36
<ul> <li>1930, L.8, pg. 336 – C</li> <li>1967, Consumers P. C</li> <li>1991 - LCRC L.3, pg. S46°E 17" Maple 49. S66°W 30" Maple 64.</li> <li>1998, LCRC L.3, pg.8</li> </ul>	Set Ironwood post for corr links, Beech 8" : pg.29 - Sec. 10 survey L.2, pg.340 –A stone long C.O. Carver- Fnd stake w/	ner of section S86°W 35 links  g set. f stones around said to h on, 20" Maple N60°E 45. se and stone, set ½" rero 17.07', S18°W 2 bipe 6.05' f 18" rebar w/cap #33978	ave been set ove 51', 14" Maple S d capped #28417 28" Maple 84.61'	35°E 55.04', 16" Maple S70°W 64.45' in center of stake
B. Description of corner evid	lence found and/or metho	od applied in restoring or	reestablishing co	orner:
and dug down 4' and for Slawson and Waterma	ound capped iron per Mito in position accepted as a	chell on W. side of stone careful & faithful perpetu	- 0.07' E & 0.05' nation of the posit	<u>-</u>
				s removed during recent road construction. in this survey. No monument reset.
C. Description of monument	for corner and accessorie	es established to perpeti	uate locating the p	position of the corner:
S70°E 40' to set blue ca N65°E 69.33' to set N& N42°W 82.34' to Fd,N& N50°E 46.99'to Fnd. na	arsonite post w/loc.tag T in S. side 24" S. Maple, C #33978 in NE. side 7" I il in SE, side 24" S.Maple T in SW. side 23" S.Maple	locust (DG), e (RM,DG),	Cap on 2 ½ " X (	Galv. Iron pipe – down 0.75'  OF MICHO  CRAIG W.  McVEAN  PROFESSIONAL  SURVEYOR
Signed by Cray	W. Muller	<u> </u>	Date <u>/ 2</u> /	13/1999 P. No. 39088
Surveyor's Michigan License	No. <u>39088</u>			A OFE SSION
		FORM APPRO	VED BY MICHIGAN STA	TE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975
UWANIMOURIY / Ghait	ACCEPTED BY THE			REVISED JAN., 1983 REVISED OCT., 1995

STATE OF MICHIGAN

GRAND TRAVERSE COUNTY

Charles Group Accepted by THE Charles ATTY PEER REVIEW GROUP CORNER UNDER MICHELL, P.S., CHÂINMAN