LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Grand Traverse (County)	Located In Corner Cor	de#
Public Land Survey	T 27N R 9W J-7	
Property Controlling in Section Miscellaneous	T	
Property in Section	S T R R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	ABCDEFGHIJKLM
5. Private Claims:		2 6 5 3 2 2 1 -
requirements of PA 74, Mic and 2 above were in confor the current manual of surv Interior, Bureau of Land Mar corner points mentioned in I of the Michigan Board of established, re-established,	eld survey on Oct. 27, 1999 do hereby state that higan PA of 1970, the corner points mentioned in mance with regulations and rules therefore as requivey instructions of the United States Department or by a decree of a Court of Law and/or the lines 3, 4 and 5 above were in conformance with the Land Surveyors or by a Decree of a Court of monumented, recovered, found as expressed below 2 corners, all in the same town and range, notificate.	ines 1 ired in 5 ired in 5 ired in 6 in 18 ired in
A. Description of original monument and accessories and/or subsequent restoration:		
 L1. Pg. 27 - W. Slavwit. W. Pine stub 3 M. Schaaf – 1934 n 	., Aspen 5" N86º ½ W 18 L. wson – 1876	LCRC L.1 P.573 – C.F. Roser - 1973 Found 4" concrete monument per Consumer's survey 18" W. Pine N28°W 24.6' 18" W. Pine S34°E 45.3' 16" W. Pine S53°W 38.4' CL firelane S. due W. 4.0' Set cedar post with location tag N 33'
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:		
J-7 - ¼ corner common to Sec. 14 & 23 – Fnd. ½ " iron in 4" x 36" long concrete mon. in firelane 'T' intersection E, W&S per Perla and Roser. This monument position was established by doubling over distance & line E. from I-7 thru a M. Schaaf Mon. at the W. 1/16 corner. No Schaaf Mon was found at J-7, appears Rd. cut probably removed it. Could find no evidence of Slawson wit. Perla conc. mon. re-establishing M. Schaaf position is accepted as a careful & faithful perpetuation of the position the original corner.		
C. Description of monume	ent for corner and accessories established to p	erpetuate locating the position of the corner:
J-7 - Replaced concrete North 33' to reset or N31°W 25.09' to s S50°W 39.13' to s S34°E 45.94' to s N58°E 42.61' to s	monument with 3 1/4 " 'Grand Traverse Co. Repedar post & set blue carsonite post with location set N&T in SW side 21" W. Pine (set N&T in SE side 22" W. Pine (set N&T in W side 19" W. Pine (set N&T in NW side 24" W. Pine scribed '	non.' brass cap on 2 ½ " x 30" galvanized iron pipe – down 0.9' n tag . CFR) CFR) CFR)
Surveyor's Michigan License No.: 39088		