LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Grand Traverse		Located		Corner Co	ide #		•				
(County)		Localca		oomer oc	ide ii						
1. Public Land Survey		T 27N T 27N	R 9W 10W	A-7 M-7	to the same and th						
Property Controlling in Section	s	T	R								
Miscellaneous Property in Section	s	T	R								
	s	Т	R				Registe	r of Deed	s Stamp	& File Nur	mber
4. Lot No:	Recorded Plat: A B C D E F G H I J K L M 1										L M
5. Private Claims:						2 - 6			-3 -		
I, <u>Craig W. McVean</u> , in a field survey on <u>October 25</u> , 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:											13
NOTE: Not more than 2 corners, all in the same town and range be recorded on this certificate.					may	10 —30 11 12 —31	32-	33	34	35	36
A. Description of original monument and accessories and/or subsequent restoration:											
A-7& M-7-GLO-set post-J. Hodgson-1839 Pine 24" N52°W 25 L. Pine 15" S17°W 25 LGLO-T27N R10W-O. Risdon-1852 W. Pine 14" N80°W 51 L. W. Pine 20" S35°W 119 LL. 1, P. 36-C.P. Tuller-1889- Sur. Sec. 19, T27N R9W-corner usedL.1, P. 74-C.P. Tuller-1889 Sur. Sec. 13 T27N R10W-FND. Post.					-M. Schaaf-1934-both SW Stps. NW holes -Consumers Power Co1967-P. Perla- 1 ¼" Iron FD. 6" Elm-N27°04'E 10.45', 6" Elm S66°40'E 9.19', 4" W. Pine S37°40'W 7.81' -LCRC L.2, P. 296-C.F. Roser-1977 FND 1 ¼" short pipe in conc. block (Schaaf Mon.) Both USBT (Pine Stps.) SW are still standing Added DNR Mon. & cedar post w/ loc. Tag 8" W. Pine N69°W 49.2', 7" Oak N29°E 10.45', 6" Oak S67°E 9.18', 4" W. Pine S35°W 7.80'						
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:											
evidence as set nail in CL dist. N. 2626	e of 4 GLO BT follows S35°V ± of definite .25′ (2640′ CF a careful & fa R Mon. & Schies S32°W 79. af notes that hydence that pridence that properties of the street of	T's. Set 3.1 V 79.37' to pine roots T & GLO) ithful perpeaaf Mon. bi 2' to CL. a ne had hole ine trees e	/4" 'Grand Tr set nail in C of Stp. and to A6-M6 & etuation of th uried along s nd a 15"± W es at both N ever occupied	raverse Co L. 20" WF S 1517°W 1 S 2655.2 he position side per P PS S19°V W GLO B1 d these loo	o. Remon.' bi PS, N80°W 3- 6.5' to depres 0' (2657.82'- 1 of the origin erla & Roser V 17.1 to face I sites. We c	rass cap 4.39' to s ssion with -CPT, 26 al corner at Schaa e that Sch dig at the	on 2 1/2" et nail ir n pieces 40'-GLO n f position haaf app se locati	x 30" ga n CL. 15 of Burn to A8- on- N51° oears to	alvanize " WPS, t Pine F M8. 3 2 02'W 30 have us n the DI	d Iron Pip N52°W 1 Root. Me 4" Brass 6.27' of A sed to esi NR monu	pe from 16.97' to asure grid Cap x7-M7. tablish his
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:											
Set Blue Ca S76°E 19.66 S4°E 41.27' N10°W 13.7 S88°W 27.1	Traverse Corpost w/ loc. Traverse Corpost w/ loc. Traverse Post v 5' to N & T in E to N & T in E '7' to N & T in 2' to S & T in 6.27' to 1 ½" l	Fag 0.7' N W loc. Tag N side 12" side 9" R. E side 10" N side 10"	to face 1' E. R. Pine scrib Pine scribed W. Pine scr Tw. R. Oak	oed 'XBT' J 'XBT' ibed 'XBT scribed 'X	, (BT'	ŕ	ing of st		CENTER	CRAIG McVEA ROFESSIN SURVEY No. 39088	ONAL BOOM
Signed by:	ming !	W	Mil	Ven		Da	te: / Z	/13/	1999	7	**************************************
Surveyor's Michigan L	icense No.:	390)88		 ,		 .				·· · · · · · · · · · · · · · · · · · ·