LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of	Act 74, Mich. PA 1970	
For Corners In: Grand Traverse (County)	Located In Corner 0	Code #	
Public Land Survey	T 27N R 9W M-6		
2. Property Controlling in Section	S T R		
Miscellaneous Property in Section	S T R S T R	Register of De	eds Stamp & File Number
4. Lot No:	Recorded Plat:	ABCDEF	GHIJKLM
5. Private Claims:		2 6 6 6 3	3 - 2 - 1
requirements of PA 74, Mic and 2 above were in confor the current manual of surv Interior, Bureau of Land Mar corner points mentioned in I of the Michigan Board of established, re-established,	eld survey on Nov. 1, 1999 do hereby state the thigan PA of 1970, the corner points mentioned mance with regulations and rules therefore as revery instructions of the United States Departmenagement or by a decree of a Court of Law and/of lines 3, 4 and 5 above were in conformance with Land Surveyors or by a Decree of a Court monumented, recovered, found as expressed be a corners, all in the same town and range tifficate.	in lines 1 equired in solution of the sor that the the rules of Law; slow:	
A. Description of original	monument and accessories and/or subsequ		
 M. Schaaf – 1930' corner set by meas MDNR corner recorder found 1" pipe in coolin line with fire line may have been set would fall in Rd. & sevidence to contrar 	Aspen 4" S89°W 13 L. 18-27-8 Survey Bk. 32, P.14 +/- surement per index rd -K.J Ostling – 1967 encrete mon. per M. Schaaf –1934. N,S,E&W t from original evidence although USBT stp. Have been removed. Unable to find y so accepted this as best available ipe with 4" Alum. cap	- Consumers Power Company – 19 Found concrete monument LCRC L.3 , pg. 614 - Grand Trave C.F Roser-1995 - found Conserva 5" Maple N60°W 22.0' 16" W. Pine N50°E 15.6' 8" Maple S60°E 46.4' 9" R. Pine S60°W 40.0' Set cedar post N45°W 16.5'	rse County record-
M-6 – Standard ¼ corner Set 3 ¼ " 'Grand Tr Centerline of N-S fil 3 ¼ " brass cap mo -Reference Pt. –Foul position that Schaaf S4°51'W 40.58' of th	vidence found and/or method applies in rest common to section 13, T27N, R9W & section averse Co. Remon.' brass cap on 2 ½ " X 3 re lane is 6.5' West. Centerline of E-W fire I n. accepted as a careful & faithful reestablished DOC (DNR) 4" Alum cap & mon S22°1 indicates he set by measurement. The M. She approved M-5 position. Thus DOC Mon. of not utilized as M-6. Removed DNR (DOC)	on 18, T27N, R8W – No GLO evidence 30" galvanized iron pipe by single propine is 24' South. Shment of the position of the original of 6'W 25.80' of M-6. This DNR mon. by Schaaf position ½ mile N was rejected couldn't be accepted as the proper.	portion between M-5 & M-7. corner y Ostling is M. Schaaf's I as M-5 being Single Proportion position
C. Description of monume	ent for corner and accessories established to	perpetuate locating the position of the	ne corner:
Reset 6" cedar post N34°E 17.11' S87°E 36.14' S45°W 62.40' N85°W 22.75' S22°16'W 25.80'	rse Co. Remon.' Brass cap on 2 ½ " X 30" g with tag N 0.85' to face to set N&T in W side 11" R. Pine scri to set N&T in S side 12" W. Pine scri to set N&T in NW side 9" R. Pine fnd to set N&T in S side 15" R. Oak scril to 1 ½" iron pipe stub in concrete tablet – g Post w/ loc. Tag 1' E	bed 'XBT' ibed 'XBT' . scribed '¼ S NBT' bed 'XBT'	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
Surveyor's Michigan Lic	A	12/13/1999	APOFF SEIONAL S