


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

GRAND TRAVERSE COUNTY
T 27 N R 10 W

DESCRIPTION OF CORNER Sec. cor common to Sections 26-27-34-35
CORNER MONUMENT 3" Found/malleable iron pipe . Added Cedar Guard post with location tag.
DATE MONUMENT PLACED AND WITNESSED 5-5-70

WITNESSES TO CORNER..... 10" Oak S 18 E 24.2'
8" Oak N 85 E 51.1'
8" R. Pine N 23 W 24.2'
AND



CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey in this area.
Pete Perla recovered this corner in April 1968, while making a survey for
Consumers Power Company.

SURVEYOR'S SEAL

SIGNED

Carl F. Roser

DATE

6/16/70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 12028

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68