Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



LAND CORNER RECORD

		r. <u>27</u> T. <u>27</u>	N.R N.R	9 W 10 W	Grand Traverse	COUNTY
DESCRIPTION OF CORNER _	1/4 Co	rner com	non to Se	ections 7-12		
CORNER MONUMENT	Set 1"	pipe wit	th 4" Ali	minum Cap		
DATE MONUMENT PLACED AN	D WITNESSED	May	5, 1966			
VITNESSES TO CORNER	••					
N		6п н. Ма	aple	s 14 W	24.51	
12		6" R. Oa	ık	N 83 E	33•71	
CIRCLE CORNER REGISTERES	AND					

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored while making a survey in Section 12. Set corner at old established fence intersection, on line between Section corners. Could find no evidence of previous corner, but this point conforms with surrounding occupation and appears to have been accepted as proper location.

SURVEYOR'S SEAL

SIGNED Much Dellewy DATE May 10, 1966

REGISTERED SAND BURVEYOR #20068