SURVEY & REMONUMENTATION

APR 2 7 1995

For corners in

LIBER 003 PAGE 582

MM	aana	ES	PART
الكسية فسيلة	IVI. VI		

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	STATE OF MICHIGAN
•	GRAND TRAVERSE COUNTY
	RECURDED
	30 DEC 90 1:36 P.M.
	KARON ANDERSON
	REGISTER OF DEEDS

Traverse	Located to:	Corner Code =++
(County)		· ·
Land Survey	T 27N R 12W	V K-9
	T R	
	T R	
	T R	
y Controlling	S T R	
ion	S T R	
aneous	S T R	
y in Sec.	S	
	County) Land Survey y Controlling ion aneous	Located In: Land Survey

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
5.	Private Claims
1	

I, Garth D. Stowe in a field survey on October 13 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 12 -- 31
 - 13 L

A. Description of original monument and accessories and/or subsequent restoration:

K-9: Original G.L.O. notes and witnesses. County Surveyors notes of 1898 filed in Liber 1, Pg. 181 and of 1909 filed in Liber 6, Pg. 195. Act 74 filed in Liber 1, Pg. 11 and Liber 1, Pg. 328.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-9: No physical evidence of original G.L.O. witnesses were found. Found cabin spike in 3-1/2" water valve in box over a 1" x 18" iron bar which was over a 1-1/4" x 18" iron bar next to a stone and replaced with Grand Traverse County monument. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

ROBERT F. MITCHELL, P.S., CITALINAN

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9: Corner common to Sections 23, 24, 25 & 26, T.27N., R.12W.

Perpetuated with 2-1/2" x 30" flanged bottom galvanized iron pipe with 3-1/4" brass cap stamped GRAND TRAVERSE COUNTY REMONUMENTATION.

N26°W 62.20' Power Pole

N26°W 62.20' Power Pole S27°W 94.08' Power Pole S13°E 86.03' Tel. Pole N47°E 60.09' Tel. Post

Corner approved by the Grand Traverse County Peer Review Grant

Signed by _______ Date ______

SURVEYOR
NO.
25875
LEO LANU SURVEYOR
LZ - Z PREPRINTED TO THE

GARTH

D. STOWE

Surveyor's Michigan Lisense No.