

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD


T. 27 N.R. 12 W  
T. 27 N.R. 13 W Grand Traverse  
Benzie COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 30-25

CORNER MONUMENT Cons. Dept. monument

DATE MONUMENT PLACED AND WITNESSED 9/22/67

WITNESSES TO CORNER.....



5" R. Oak N 48 E 10.4'

18" W. Pine Stub S 64 W 32.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners. Could identify no previous corner.

SURVEYOR'S SEAL

SIGNED *Lenneth J. Ostling* DATE 11/20/67  
REGISTERED LAND SURVEYOR #20068