## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>27</u> N. R. <u>12 W</u>

		GF	AND TRAVERSE COUNTY
DESCRIPTION OF CORNER _	1/4 corner common to see	tions 19-30	· · · · · · · · · · · · · · · · · · ·
CORNER MONUMENT	Set 5' of 1" pipe in mu	k area; and squared	cedar guard post.
DATE MONUMENT PLACED AND	WITHESSED 2/7/68		
WITNESSES TO CORNER			
N N	5" Tamazzk	S 70 W	3.8'
3ô	8" Tamarack	Due S	20.3'
CIRCLE CORNER REGISTERED	Cor. is 2.8' S	of E-W Random Line	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by single proportion between section corner to east and west. The corner fit the calls in the GLO notes for a small lake and hemlock ridge very close when consideration was given to the fact that the GLO calls were taken on a random line.

SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR 12028