MAR 1 6 1994

## COLOMESION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

E۵	r carners in	i mig riequi	QIIIGI:	if At MAC 1.4' impair a				
	GRAND TRAVERS	E Located In:		Corner Code ##				
	(County)						,	
1	Public Land Survey	T	/ 1	M-7		STATE OF	MICHIGAN	
١.	r doile Earla Garvey	T R				Grand Trave		1
		T R	_			RECÇ	RED	
		T R				70 PCD 07	ATT A M	
2.	Property Controlling	S T R				30 DEC <u>93</u>	In: 1X H'U'	1
_	in Section	S T R				VARON (	WITERSON	
3.	Miscellaneous Property in Sec.	S T R S T R		·	Registe	er of Deeds Stan	HE RES	lumber
	Property in Sec.	· ·						
4.	Lot No	lecorded Plat				ABCDE	F G H I	JKLN
					2	- 6- - 5-	!- -}-	-;:-
					3			111
	Gary G. Wilson	<b>D</b>	vemh	or 17	03 .	1-1-8-1-	9-10-1	-1112-
l, _	horsby certify that under re	, in a field survey on	A of 197	O the corner points mer	diagod			
in	lines 1 and 2 above were in	n conformance with regulations a	ind rule	es therefore as required	I in the		6	14
cu	rrent manual of survey instr	uctions of the United States Department	artment	of the Interior, Bureau of	of Land '			
Ma	anagement or by a decree or love were in conformance wi	a Court of Law and/or that the corr th the rules of the Michigan Board	er poir Lof Lan	d Surveyors or by a Dec	roo of a	13 7 20 7	22	2324 
Co	ourt of Law; established,	re-established, monumented, re	-monui	mented, recovered, for	und as		<del>                                     </del>	-
	pressed below:				10	1 1	827	2625
N		orners, all in the same town	and ra	nge, may be recorde				-
	on this certificate.				12	1 1 1 1 1	34	35 36
Α.	Description of original	monument and accessories a	nd/or :	subsequent restoration	13 on:	·	<del> </del>	
	(per Liber 2, Pg. 404 a and Liber 10, Pg. 89).	C.P. Tuller found post and and Liber 2, Pg. 372). In N In September 1972, W.B. I were filed: in June 1974 by tent; in May 1975 Richard ie/Fraser & Assoc. found i	oveml Batzer Gosl	ber 1911, E.P. Wate Act 74 & Act 132 s ing. Czubak & Asso	erman found ( survey found oc. found 2" i	2" iron stake (p 2" iron pipe in iron pipe: in Au	er Liber : centerline gust 1974	5, Pg. 198 e of gravel l Richards
В.	Description of corner e	evidence found and/or method	t appli	ed in restoring or ree	stablishing co	rner:		
	A 1/2" rebar f	ience of the original GLO vound in monument box in a said rebar matches old E	enterl	ine of Townline Ro	oad raser v	witnesses.		
C.		ent for corner and accessorie	s estal	plished to perpetuate	locating the p	position of the co	orner:	
	TRAVERSE (	ith 2-1/2" X 30" flanged be COUNTY REMONUMENT	ottom CATIC	galvanized iron pip DN.	e with 3-1/2"	brass cap stan	nped GRA	AND
	N/9°W 47.93 N75°W 44.90	' 10" Cedar (Dead) ' 10" Cedar stump				Y 18 22	ARY C.	
	S40°E 46.7' 1	' 10" Cedar stump 0" White Birch stump				,	AUTOM .	
	N38°E 113.09	)' 10" Tamarack					LAND	T CO
	S52°W 44.23	to robial				ध्"ः ७	uhveyor — Mo.	* # []
	Corner approved by the	ne Grand/Traverse County	Peer F	Review Group on 12	2-15-93.		25681 -	· & A
		l. lall			<del></del>	25.50		Mar John
	رر در ک	10 Wilson		<b>.</b>	,	Dagambar 70%	1602 mili	Illy r
Si	igned by Gary G. V	vilson, PS	_	Date _		December 28;	1939W	
S	urveyor's Michigan Licen	·	5881		FORM APPROVED	BY MICHIBAN STATE BOAI	D OF LAND SURV	EYORS, JAN. 20, 1

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983