

UBER 1003 IN: 735

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Grand Traverse (County)	Located In:	Corner Code #	STATE OF MICHIGAN GRAND TRAVERSE COUNTY RECORDED
Public Land Survey	T <u>28N</u> R <u>9W</u> T R	C-6	30 DEC 96 12:25 P.H.
 Property Controlling in Section Miscellaneous Property in Section 	T R T R ST R ST R ST R ST R	Jeg. #2	KARON ANDERSON. REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, P. 5. Private Claims	lecorded Plat		A B C D E F G H I J K L M
do hereby certify that under rec in lines 1 and 2 above were in c manual of survey instructions Management or by a decree of 5 above were in conformance	Lin a field survey on November 1997. November 2007. Note that the column a Court of Law and/or that the column the rules of the Michigan Boblished, re-established, monument	A. of 1970, the corner points meniules therefore as required in the cent of the Interior, Bureau of the points mentioned in lines 3, and of Professional Surveyors or	Eurrent 7
on this certificate.	rners, all in the same town and	range, may be recorded	11

- 1/4 Cor common to Secs 17 & 18, T28N-R9W; "A 2 1/2" x 30" flanged bottom galvanized iron pipe with a 3 1/2" brass cap stamped GRAND TRAVERSE CO REMONUMENTATION, in a monument box, 2" below the surface of a North-South black top road", a LCR by Robert F. Mitchell, recorded under the Grand Traverse County Remonumentation plat and approved by the peer review group on Nov 7, 1995 and recorded in L.3, Pg.628 of the LCR's of Grand Traverse Co. A complete history of this cor is C-61 recorded on this Land Cor Certificate.
 - B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1/4 Cor common to Secs 17 & 18, T28N-R9W; Bates Road went through a major reconstruction project in the Fall of 1995 and the Summer of 1996, the existing approved Co. Remon monument was removed and destroyed by this constructuion. Re-established this corner with a 2 1/2" x 30" flanged bottom galvanized iron pipe with a 3 1/4" brass Cap stamped GRAND TRAVERSE COUNTY REMONUMENTATION, 4" below the surface of an North-South black top road, in a monument box, from 3 remaining wits of the previously recorded Remonumentation LCR as recorded in L.3, Pg.628 and is accepted as a careful and faithful perpetuation of the position of the original corner, as decumented in L.3. Pg.628 of the LCR/2 of Careful Management of the position of the original corner, as accepted as a careful and faithful perpetuation of the position of the original corner, documented in L.3, Pg.628 of the LCR's of Grand Traverse Co.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-6) 1/4 Cor common to Secs 17 & 18, T28N-R9W;

A 2 1/2" x 30" flanged bottom galvanized iron pipe with a 3 1/4" brass Cap stamped GRAND TRAVERSE COUNTY REMONUMENTATION, in a monument box, 4" below the surface and 2.5 feet East of the centerline of North-South Bates Road.

S81°W - Power Pole - 29.31' (old wit L.3, Pg.628)
N44°W - 20" Maple - 142.87' (old wit L.3, Pg.628)
N45°E - Service Pole - 115.80' (old wit L.3, Pg.628)

Apple - 63.62'

Date

UNANIMOUSLY ACCEPTED BY THE GRAND TRAVERSE COUNTY PEER REVIEW GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON 12-13-96

ROBERT F. MITCHELL, PS., CHAIMAN

Signed by 28417 Surveyor's Michigan License No.

กก 28417 STO LAND SU

-abitati da

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976 REVISED JAN., 1983