

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 50 N.R. 36-37 W


Houghton COUNTY

DESCRIPTION OF CORNER Typ. Corner - T 50N Rs³⁶⁻³⁷ W, on the 5th Correction Line

CORNER MONUMENT 1/2" Iron bar buried in center of N-S Road

DATE MONUMENT PLACED AND WITNESSED 7/27/1966

WITNESSES TO CORNER..... Culvert North 75.6 Feet



36" W. Pine Str., S 23° E, 42.5 Feet

Cedar Post Location Poster, East, 17.5 Feet

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Placed 1/2" Iron in Center of Road from South and opposite an old Cedar Post
with location Poster, which stands on East side of road.

Stream to East.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
REGISTERED LAND SURVEYOR DATE 8/12/1966