CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 51 N.R. 35 W

	Houghton	_ COUNTY
DESCRIPTION OF CORNER Section Corner common to Secs	. 1 2-3-10-11	<u>_</u>
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap		
DATE MONUMENT PLACED AND WITHESSED 4/13/1966	Distances in Feet	
WITHESSES TO CORNER 16" Soft Maple (S10 NBT) S	50° W . 22.71	
9 Soft Maple (S11 NBT).	S 41 E, 56.01	
AND CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner replaced at an old Corner location.

Found two down cedars, blazed facing the corner.

Position checks with streams to North-East and South; and with other corners in area.

SURVEYOR'S SEAL

Billy & Buckler.

IGNED Billy D. Buckler

DATE 6/3/1966