

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 51-52N N.R. 35W


Benighton COUNTY

DESCRIPTION OF CORNER 1/2 corner between Sections 2-35

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 6-19-62

WITNESSES TO CORNER,..... 9" soft maple (1/2 S NBT) S66°W, 33 links



17" W. Spruce (1/2 S NBT) N30°W, 52 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established midway and on line between two section corners. Found no evidence of original corner. 30 links N. of 40 marker.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler