

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51. NR. 35. W.
T. 52. NR. 35. W.

----- Houghton ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 3, 4, 33, 34 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 10" Hemlock - N 24 E - 76 Links -----

10" Y. Birch - N 72 W - 99 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located by unknown Surveyor. Checks o.k. by proportionate measurement. Remains of two probable B.T.'s still in place, badly rotted.

Corner was placed and witnessed August 27, 1953.

SURVEYORS SEAL

SIGNED Dean C. DeSmet DATE 1/15/54
REGISTERED LAND SURVEYOR