MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T51-52 NR _ 35 _ W

DESCRIPTION OF CORN	IER Section_corner_common_to_Sections_5,_6, 31, and 32
DESCRIPTION OF CORNI	ER MONUMENT_1" Pipe with 4" Brass Cap
WITNESSES TO CORNE	R 10" Hard Maple (S 6 NBT) S 25° W 83 Links
	8" Hard Maple (S 31 NST) N 41° W 32 Links
	10" Hard Maple (S 32 NBT) N 55° E 63 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was eplaced from Y ellow Birch B. T. bearing N 36° E 62 Links. Tree green and in excellent condition. Found iron pipe at corner.

Corner was placed and witnessed October 15, 1959.

SURVEYORS SEAL

SIGNED Suckles

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/29/60 _