

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51 N.R. 35 W


Houghton COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 11-12-13-14

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/22/1966 Distances in Feet

WITNESSES TO CORNER..... 15" Cedar (S14 NBT), S 16° W, 36.6'



CIRCLE CORNER REGISTERED

9" W, Spruce (S12 NBT), N 35° E, 11.2'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Squared and Scribed 7" Elm at Section Corner.

Placed Corner at a Fence Corner, with fence running South and East.

Streams both North and South check well.

Corner lies at bottom of a steep bank facing South.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6/3/1966
REGISTERED LAND SURVEYOR