## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

					Houghton	-	_COUNTY
				T	<u> </u>	R_	35W
DESCRIPTION OF CORNER _	1/4 corner	between	Section	ns 10 a	nd 11		
CORNER MONUMENT	1" I.D. x	36" iron	pipe w	lth 4"	aluminum o	<b>a</b> p	,
DATE MONUMENT PLACED AND	WITNESSED _	<b>ी</b> धो	y 2, 19	69			
WITNESSES TO CORNER	Balsem 3	824°E	2 1ks.	"1/48,	MBT"		
N	Belsen 3	N54°E	9 lks.	*1/ <b>4</b> 8,	MBT"	<del></del>	
10	AND						
CIRCLE CORNER REGISTERS	ED					·· <del>-</del> · · · ·	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed on line between section corners 39.66 chains to north and south. Found no evidence of original post or its accessories or of any replacement monument or accessories. Distance north to a stream crossing shows close agreement with original field notes. Corner lies on side of a steep hill running about north and south at this place.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

SIGNED

REGISTERED LAND SURVEYOR

DATE 1/22/1/

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68