LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing	Requirement of Act 74, N	lich. P.A. 197	70							
Houghton											
	Located in:	Corner Code #									
(County)											
1. Public Land Survey	T51H R 3	6N K5									
	TR TR										
	TR										
2. Property Controlling in Section	S TR S T R										
3. Miscellaneous	s † R										
Property in Sec.	S TR			Re	nieta	r of De	eds St	amn £	File	Mumi	har
					giste	or De	eus St	amp a	FILE	NUITA	Dei
4. Lot No, Reco	rded Plat										
5. Private Claims				1 A	в с I I	D E	FG	H	I J	K	L M
				2	6-		4	∮-	<u></u>	+	-
. Observat V. Osmanland i		ar 14 2000		3	+-+	- -					-
I, Stephan J. Szyszkoski requirements of P.A. 74, Michiga	, in a field survey on an PA of 1970 the corner r	, 19 do hereby s	tate that under	4	<u>;</u> —	- è-	ģ	10	-1	-	-12
conformance with regulations and	I rules therefore as required in	n the current manual of survey inst	ructions of the	5		+				•	
United States Department of the that the corner points mentioned	Interior, Bureau of Land Mana In lines 3, 4 and 5 above we	agement or by a decree of a Court re in conformance with the rules o	of Law and /or f the Michigan	6 -1	18-	-17-	-16-	1 5	1	+	-13
Board of Land Surveyors or by recovered found as expressed be	a Decree of a Court of L	aw; established, re-established,	monumented,	7	\Box				\vdash		-
•				81	9 	-20 	21	22 	2:	+	-2 '4
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town a	nd range, may be recorded		9					11		-
Off units Continuate.				10	1	29 	28 	27 	1-26	7	25
				11 -3		32	3,	74	35		-36
				13	ΪΤ	Ĭ	ĭ		Τì		- 36
5" Maple S55E 36.1'. The 197 N01-00'-21"W, 39.701; S87-24' 1/4 corners to the east and s	-30"W, 40.265; S00-46'-:	11"E, 39.708; and 889-55'-5	6"E, 40.1885;	all to	adja	cent 1	/4 corn	ers.	Also,	the	
B. Description of corner evid	dence found and/or metho	od applied in restoring or rees	tablishing corne	er:							
(KS) Did not recover the 1990 the corner in the 1990 locati 1970 position was erroneously 1970 position. I remonumente north, south, east, and west, I placed a 1° ID x 32° iron p 1990 is N71E, 13.6' from the	on. The 1990 position : monumented, as a resul- d the corner at the 1970 and the direction of the ipe capped with a 4" dia	is at odds with measurement: t of a blunder, or that the O record position by harmon he monumented section lines	s made by A.O. 1990 position izing the 1970 to the east a	Enger was no record nd sou	in 19 ot an d mea th.	70. I accura surement At the	t appea ate per nts to positi	rs tha petuat Quarte on for	t eit ion o r cor the	her to the ners	the e er
C. Description of monument (K5) Set 1" pipe with 4" MDNR Blazed and scribed the follow 7" Maple S69E 45.8' "S13 7" Maple S46E 20.3' "S13 9" Maple S52W 18.5' "S14 Distances are to notch in low Power pole N47W 57.2' PK nail Bearings are magnetic.	cap. ing: NBT" NBT" NBT" er blaze.	es established to perpetuate lo	STEP SZYS: LA SURV	HAN .		orner:					
Signed by <u>Slepher</u> Surveyor's Michigan License N	J. Snyzks	<i>θ</i> 6	Date 5	11/2	000						